OMB Control No.: 2127-0004

Not sequential

Part 573 Safety Recall Report

19V-371

Manufacturer Name: Daimler Trucks North America LLC

Submission Date: MAY 14, 2019 NHTSA Recall No.: 19V-371 Manufacturer Recall No.: FL-814



Manufacturer Information:

Manufacturer Name: Daimler Trucks North America LLC

Address: 4747 N. Channel Avenue

Portland OR 97217-3849

Company phone: 800-745-8000

Population:

Number of potentially involved: 9,702 Estimated percentage with defect: 12 %

Vehicle Information:

Vehicle 1: 2012-2019 Freightliner Custom Chass MT55

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: MT45 and MT55 Chassis equipped with certain hydraulic brakes and brake switch

configuration built within the above referenced dates.

Production Dates: JAN 12, 2011 - JAN 03, 2019

VIN Range 1 : Begin : NR End : NR

Vehicle 2: 2012-2019 Freightliner Custom Chass MT45

Vehicle Type : Body Style : Power Train : NR

Descriptive Information: MT45 and MT55 Chassis equipped with certain hydraulic brakes and brake switch

configuration built within the above referenced dates.

Production Dates: JAN 12, 2011 - JAN 03, 2019

VIN Range 1 : Begin : NR End : NR Not sequential

Description of Defect:

Description of the Defect: Brake pedal clevis pin clip may rub or bend on the throttle pedal mounting

hardware. There is a potential the pin clip may become detached.

FMVSS 1: NR FMVSS 2: NR

 $Description\ of\ the\ Safety\ Risk:\ If\ the\ clip\ is\ detached\ and\ the\ clev is\ pin\ slides\ out\ of\ position,\ there\ will$

initially be loss of brake lights. If the pin continues to slide out further, the pedal may become detached. The detached pedal is still located such that

The information contained in this report was submitted pursuant to 49 CFR §573

activation of the brake may be possible, but it is expected that such activation may require increased pedal pressure. Loss of brake lights may increase the risk of a crash, if following vehicles are unaware the vehicle is slowing or stopping, and an increase in required pressure for brake activation may cause driver confusion and could also increase the risk of a crash.

Description of the Cause: NR
Identification of Any Warning NR
that can Occur:

Supplier Identification:

Component Manufacturer

Name: NR Address: NR

NR

Country: NR

Chronology:

In March 2019, Freightliner Custom Chassis Corporation (FCCC) received a report of an incident reportedly involving a vehicle not having service brakes, because the clevis pin on the brake pedal may have slid out of position. March to April 2019, FCCC inspected the customer's fleet to confirm the issue. DTNA's review identified multiple vehicles with damaged clevis pin clips in the customer's fleet. On May 8th, 2019 DTNA decided to conduct a voluntary safety recall after careful consideration of the possible impacts of the issue.

Description of Remedy:

Description of Remedy Program: Potentially affected vehicles will be inspected and repaired as necessary.

Repairs will be performed by Daimler Trucks North America authorized service facilities. Copies of the reimbursement plan will be submitted as a

supplemental report when available.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule : Customer notification will be made by first class mail using Daimler

Trucks North America records to determine the customers affected.

Part 573 Safety Recall Report

19V-371

Page 3

Planned Dealer Notification Date : JUL 12, 2019 - JUL 12, 2019 Planned Owner Notification Date : JUL 12, 2019 - JUL 12, 2019

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573