#### OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

## 20V-086

**Manufacturer Name:** PACCAR Incorporated

NHTSA Recall No.: 20V-086

Manufacturer Recall No.: 20KWA



#### **Manufacturer Information:**

Manufacturer Name: PACCAR Incorporated

Address: 777 106TH AVENUE NORTHEAST

**BELLEVUE WA 98004** 

Company phone: 940 591 4220

## **Population:**

Number of potentially involved : 4 Estimated percentage with defect : 100 %

#### **Vehicle Information:**

Vehicle 1: 2020-2020 Kenworth T370

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER Power Train : DIESEL

Descriptive Information: Long wheelbase vehicles with larger rear axle spacing are affected. This is a relatively

new and very low volume option for the T370.

Production Dates: APR 23, 2019 - SEP 30, 2019

VIN Range 1 : Begin : NR End : NR Not sequential

#### **Description of Defect:**

Description of the Defect: A second R12 relay valve was not installed on the vehicle.

FMVSS 1: 121 - Air brake systems

FMVSS 2: NR

Description of the Safety Risk: Without the second R12 relay valve installed, the rear brakes will exhibit an

increase in brake activation timing that is non-compliant per FMVSS 121. Increased brake activation timing may lengthen vehicle stopping distance during an emergency braking event, which may increase the risk of an

accident, personal injury and/or property damage.

Description of the Cause: The production plant did not identify the second valve call-out was required

for certain configurations of vehicles. As a result, they did not install the

second valve as required.

Identification of Any Warning None.

that can Occur:

## **Supplier Identification:**

### **Component Manufacturer**

Name: Kenworth Truck Company

Address: 10630 NE 38th Place

Kirkland WASHINGTON 98033

**Country: United States** 

#### **Chronology:**

11-13-19: The Ste Therese plant noticed dual valve callouts on a chassis and was uncertain if this was an error. Engineering confirmed correct callouts.

11-15-19: Engineering reported to safety and compliance. Trucks requiring dual R12 relay valves were held at the factory and Active Transport until rework could be performed.

01-23-19: Engineering provided a summary of brake timing impact to safety and compliance team for review.

2-13-20: Kenworth Safety Committee decided this condition constitutes a defect relating to motor vehicle safety for which a voluntary recall should be initiated.

#### **Description of Remedy:**

Description of Remedy Program: To remedy this defect, Kenworth dealers will inspect vehicles in the

affected population. If the additional valve is not present, they will update

the brake plumbing to include a second R12 relay valve as needed.

How Remedy Component Differs The recalled vehicle does not include the additional relay valve.

from Recalled Component:

Identify How/When Recall Condition Potentially affected vehicles were held at the plant for inspection and was Corrected in Production: installation of the second relay valve as required. Assembly personnel

were trained and informed to install the second relay valve when required.

#### Recall Schedule:

Description of Recall Schedule: NR

Planned Dealer Notification Date: NR - NR Planned Owner Notification Date: NR - NR

\* NR - Not Reported