

# Part 573 Safety Recall Report

# 20V-203

**Manufacturer Name :** Marion Body Works Inc.**Submission Date :** APR 08, 2020**NHTSA Recall No. :** 20V-203**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Marion Body Works Inc.

Address : 211 West Ramsdell St.

Marion WI 54950

Company phone : 715-754-5261

**Population :**

Number of potentially involved : 9

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2019-2020 Spartan Gladiator and MetroStar

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : Spartan Fire, LLC has decided that a defect which relates to motor vehicle safety exists in certain model year 2019-2020 Gladiator and MetroStar model emergency response chassis cabs.

Production Dates : OCT 22, 2019 - JAN 21, 2020

VIN Range 1 : Begin : 4S7AV2E95LC087954 End : 4S7AV2E95LC088148  Not sequential**Description of Defect :**

Description of the Defect : On the affected vehicles, the park brake control line may loosen.

FMVSS 1 : 121 - Air brake systems

FMVSS 2 : NR

Description of the Safety Risk : If the air line comes out of the fitting while the vehicle is in motion, the park brake can inadvertently be applied. If the park brake inadvertently sets, the driver could be startled or the vehicle could suddenly decelerate without brake light activation, which could increase the risk of a crash. This could occur without warning.

Description of the Cause : NR

Identification of Any Warning NR  
that can Occur :

**Involved Components :**

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

## Supplier Identification :

### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

## Chronology :

Spartan Fire, LLC has decided that a defect which relates to motor vehicle safety exists in certain model year 2019-2020 Gladiator and MetroStar model emergency response chassis cabs.

## Description of Remedy :

Description of Remedy Program : Manufacturer will inspect for appropriate tightness and tighten when necessary. Inspection and tightening may take up to 1 hour.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

## Recall Schedule :

Description of Recall Schedule : All 9 units have not been delivered to owners. Inspections will be done and repaired when necessary prior to delivery.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported