OMB Control No.: 2127-0004

Part 573 Safety Recall Report

Manufacturer Name :Motor Coach IndustriesSubmission Date :AUG 31, 2020NHTSA Recall No. :20V-526Manufacturer Recall No. :SB 486

Manufacturer Information :

Manufacturer Name : Motor Coach Industries Address : 200 East Oakton Street Des Plaines IL 60018 Company phone : 1-800-241-2947

Vehicle Information :

Vehicle 1:	2017-2020 M	CI D4505			
Vehicle Type :	BUSES, MEDIU	JM & HEAVY VE	CHICLES		
Body Style :	OTHER				
Power Train :	DIESEL				
Descriptive Information :	the coolant ho shut down sec to be spilled o the point of di built starting f vehicles not in	ses may fail, res quence. As a res n the roadway. sablement. The from model yea acluded in the re	sulting in a low co sult of the hose fa Additionally, the recall populatio r 2017 using coo	oolant warning follo ailing, engine coolan e bus may not be ab n was determined t lant hoses from Pur rior to model year 2	owed by an engine at has the potential le to be driven from o be all vehicles rosil (supplier). The
Production Dates :	JUN 07, 2016	- AUG 03, 2020			
VIN Range 1:	Begin :	NR	End: NR		Not sequential
	OTHER	JM & HEAVY VE	CHICLES		
Descriptive Information :	the coolant ho shut down sec to be spilled o the point of di built starting f vehicles not in	ses may fail, res quence. As a res n the roadway. sablement. The from model yea acluded in the re	sulting in a low co sult of the hose fa Additionally, the recall populatio r 2017 using coo	oolant warning follo illing, engine coolan e bus may not be ab n was determined t lant hoses from Pur rior to model year 2	owed by an engine at has the potential le to be driven from o be all vehicles rosil (supplier). The
Production Dates :	JUN 07, 2016	- AUG 03, 2020			

NHTSA

20V-526

Population :

Number of potentially involved : 3,598 Estimated percentage with defect : 5%

Part 573 Safety Recall Report

TT 1 + 1 - 0					
	2017-2020 M				
Vehicle Type :		UM & HEAVY	VEHICLES		
Body Style :					
Power Train :	DIESEL				
Descriptive Information :	the coolant h shut down se to be spilled o the point of d built starting vehicles not i	oses may fail, equence. As a on the roadwa lisablement. 7 from model y ncluded in th	resulting in a result of the h ay. Additionall The recall popu year 2017 usin	low coolant war ose failing, engi ly, the bus may : ulation was dete g coolant hoses puilt prior to mo	d J4500 model buses in which rning followed by an engine ne coolant has the potential not be able to be driven from ermined to be all vehicles from Purosil (supplier). The odel year 2017, or have
Production Dates :	JUN 07, 2016	- AUG 03, 202	20		
VIN Range 1:	Begin :	NR	End: N	IR	Not sequential
Vehicle Type : Body Style : Power Train :	OTHER DIESEL The recall inv the coolant h shut down se to be spilled of the point of d built starting vehicles not i coolant hoses JUN 07, 2016	UM & HEAVY volves certain oses may fail, equence. As a on the roadwa lisablement. ' from model y ncluded in th s supplied fro	2017 – 2020 M resulting in a result of the h ay. Additional The recall popu year 2017 usin e recall were b m a different s	low coolant war ose failing, engi ly, the bus may : ulation was dete g coolant hoses uilt prior to mo upplier.	d J4500 model buses in which rning followed by an engine ne coolant has the potential not be able to be driven from ermined to be all vehicles from Purosil (supplier). The odel year 2017, or have
Vehicle Type : Body Style : Power Train :	OTHER DIESEL The recall inv the coolant h shut down se to be spilled of the point of d built starting vehicles not i	UM & HEAVY volves certain oses may fail, equence. As a on the roadwa lisablement. T from model y ncluded in th	2017 – 2020 M resulting in a result of the h ay. Additionall The recall popu year 2017 usin	low coolant war ose failing, engi ly, the bus may : ulation was dete g coolant hoses puilt prior to mo	d J4500 model buses in which rning followed by an engine ne coolant has the potential not be able to be driven from ermined to be all vehicles from Purosil (supplier). The odel year 2017, or have
Production Datas.					
r rouucion Dales '					
Production Dates : VIN Range 1 :		NR	End: N	JR	Not sequential

20V-526

Page 3

Description of Defect :

Description of the Defect	The defect is that the coolant hose may fail, resulting in a low coolant warning followed by an engine shut down sequence. As a result of the hose failing, engine coolant has the potential to be spilled on the roadway. Additionally, the coach bus may not be able to be driven from the point of disablement, which might require another bus to pick up the passengers and result in loading and unloading on the side of the road.
FMVSS 1	: NR
FMVSS 2	: NR
Description of the Safety Risk	: The defect may result in increased risk of personal injury due to another vehicle potentially colliding with a disabled bus; from passengers needing to disembark the disabled vehicle and enter a replacement vehicle at roadside; and/or from other vehicles experiencing reduced traction if they are unable to avoid spilled coolant on the roadway.
Description of the Cause	: The cause is a rupture of the coolant hose. This may be a result of the liner seam not being fully fused during the curing cycle.
	A low coolant telltale will illuminate once engine coolant drops below the minimum level.
Involved Components :	
-	Tube - hot water supply
Component Description :	Tube - hot water supply
Component Part Number :	16-11-1970

Component Name 2:	Hose - Coolant, 90 deg elbow
Component Description :	Hose - Coolant, 90 deg elbow
Component Part Number :	06-08-1006

Component Name 3 :	Hose - hump, coolant
Component Description :	Hose - hump, coolant
Component Part Number :	6L-8-353

Supplier Identification :

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Component Manufacturer

Name : Purosil LLC Address : 708 S. Temescal Street Corona CALIFORNIA 92879 Country : United States

Chronology :

As a result of reports submitted by MCI through the TREAD system, the NHTSA Office of Defects Investigation opened ODI PE20-001 in April 2020.

MCI submitted its response to NHTSA's information requests in June 2020. After reviewing warranty data from Q3 2019 through Q2 2020 for all MCI coaches (D-series and J-model), and after further discussions with NHTSA, MCI decided in August 2020 to conduct a safety recall of the affected D-series and J-model buses to replace the three hoses referenced above.

Description of Remedy :

	Description of Remedy Program :	MCI will issue a Field Change Program to replace the subject hoses with a hose from a different supplier, at no charge to vehicle owners.
	5 1	The hoses from the alternate supplier have not seen failures or the potential defect identified in the subject hoses.
Ide	5	The recall condition was corrected on the three hoses at different times by changing the hose supplier from Purosil to Flex Tech.
		16-11-1970 changed Nov 23, 2018 06-08-1006 changed July 26, 2019 6L-8-353 for J Model changed March 27, 2020; for D series changed July 30, 2020.

Recall Schedule :

Description of Recall Schedule :	MCI will mail customer notification letters and service bulletins within
	seven (7) days after NHTSA approval.
Planned Dealer Notification Date :	SEP 30, 2020 - SEP 30, 2020
Planned Owner Notification Date :	SEP 30, 2020 - SEP 30, 2020

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573