Part 573 Safety Recall Report

Manufacturer Name :Ford Motor CompanySubmission Date :MAY 07, 2021NHTSA Recall No. :21V-324Manufacturer Recall No. :21S21

Manufacturer Information :

Manufacturer Name : Ford Motor Company Address : 330 Town Center Drive Suite 500 Dearborn MI 48126-2738 Company phone : 1-866-436-7332

Vehicle Information :

Vehicle 1:	2019-2019 FORD TRANSIT: T150, T250, T350		
Vehicle Type :	IGHT VEHICLES		
Body Style :	ALL		
Power Train :	GAS		
Descriptive Information :	 Ford's team reviewed supplier process, maintenance records and field data to determine the population of affected parts. Affected vehicles are equipped with a single rear wheel 410L axle and aluminum alloy wheels. This concern does not affect vehicles equipped with steel wheels. These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database. 2503 Transit vehicles are affected. 		
Production Dates .	APR 01, 2019 - JUN 28, 2019		
VIN Range 1:			
virvindige 11.			
Description of Defect :			
Description of the Defe	ct : Flange flatness on axle shafts does not meet the parallelism specification leading to possible loss of clamp load on the wheel studs. Loss of clamp load can progress into the fracture of one or more attaching studs. If all attaching studs fracture while driving, the tire and wheel assembly could detach from the vehicle.		
FMVSS	1: NR		
FMVSS	2: NR		
The information contained in this report was submitted pursuant to 49 CFR §573			
i në ir	formation contained in this report was submitted pursuant to 49 CFR §573		



21V-324

Population:

Number of potentially involved : 2,503 Estimated percentage with defect : $10\ \%$

Part 573 Safety Recall Report

Page 2

Description	of the Safety Risk : Loss of clamp load can progress into the fracture of one or more attaching studs. Fracture of all five attaching studs while driving would result in tire and wheel detachment from the rear axle of the vehicle, increasing the risk of crash.
Descriț	otion of the Cause : Excess convexity of the axle flange face may cause a loss of clamp load on one or more of the wheel attaching studs. Aluminum wheels may not flex sufficiently to conform to an out of specification axle shaft flange face.
Identificatio	on of Any Warning Wheel studs and nuts that loosen or individually fracture may lead to vibration that can Occur : and noise while driving.
nvolved Co	mponents :
Comj	oonent Name 1: Shaft Asy – Rear Axle
Compon	ent Description : Single Rear Wheel Axle Shaft
Compone	nt Part Number : KK4Z-4234-A
upplier Ide	entification :
~	
-	t Manufacturer
Name :	Guru Nanak Auto Enterprises Ltd
Name : Address :	Guru Nanak Auto Enterprises Ltd G T Road,
Name : Address :	Guru Nanak Auto Enterprises Ltd G T Road, Jamalpur Phagwara Foreign States 144632
Name : Address : Country :	Guru Nanak Auto Enterprises Ltd G T Road, Jamalpur Phagwara Foreign States 144632 India
Name : Address : Country :	Guru Nanak Auto Enterprises Ltd G T Road, Jamalpur Phagwara Foreign States 144632 India
Name : Address : Country :	Guru Nanak Auto Enterprises Ltd G T Road, Jamalpur Phagwara Foreign States 144632 India
Name : Address : Country :	Guru Nanak Auto Enterprises Ltd G T Road, Jamalpur Phagwara Foreign States 144632 India
Name : Address : Country :	Guru Nanak Auto Enterprises Ltd G T Road, Jamalpur Phagwara Foreign States 144632 India
Name : Address : Country : hronology	Guru Nanak Auto Enterprises Ltd G T Road, Jamalpur Phagwara Foreign States 144632 India

The information contained in this report was submitted pursuant to 49 CFR §573

Description of Remedy :		
Description of Remedy Program :	Owners will be notified by mail and instructed to take their vehicle to a Ford or Lincoln dealer to have the rear axle shafts inspected for convexity and if necessary, the rear axle shaft assembly, axle shaft mounting bolts, and rear wheel lug nuts will be replaced. There will be no charge for this service.	
	Ford provided the general reimbursement plan for the cost of remedies paid for by vehicle owners prior to notification of a safety recall in May 2021. The ending date for reimbursement eligibility is July 9, 2021.	
	Ford will forward a copy of the notification letters to dealers to the agency when available.	
	The supplier modified their machining process to improve flange flatness, and a tighter flatness specification was introduced. New Single Rear Wheel Axle Shafts, Shaft Asy – Rear Axle (KK4Z-4234-B) contain a flatter wheel mounting surface on the axle shaft flange.	
Identify How/When Recall Condition NR		
was Corrected in Production :		
Recall Schedule :		
Description of Recall Schedule :	Notification to dealers is expected to occur on May 14, 2021. Mailing of owner notification letters is expected to begin June 21, 2021 and is expected to be completed by June 25, 2021.	
Planned Dealer Notification Date :	MAY 14, 2021 - MAY 14, 2021	
Planned Owner Notification Date :	JUN 21, 2021 - JUN 25, 2021	

* NR - Not Reported