219

NR

# Part 573 Safety Recall Report

Manufacturer Name :New Flyer of America, Inc.Submission Date :FEB 15, 2023NHTSA Recall No. :23V-083Manufacturer Recall No. :R23-002

### Manufacturer Information :

Manufacturer Name : New Flyer of America, Inc. Address : 711 Kernaghan Avenue

Company phone : 204-224-6706

### Vehicle Information :

Vehicle 1 : Vehicle Turne :	2021-2023 New	Flyer XE35, XE	40, XE60		
venicie Type :	BUSES, MEDIUM & HEAVY VEHICLES				
Body Style :	OTHER				
Power Train :	NR				
Descriptive Information :	The recall popula	ation was deter	rmined bas	sed on the specific type o	f ESS used.
	Product differen	ce will be deter	mined wh	en the remedy is defined	I.
	Affected models	and MY:			
	2021 XE35 - 8				
	2022 XE35 - 28				
	2021 XE40 - 71				
	2022 XE40 - 83				
	2023 AE40 - 3 2021 VE60 - 24				
	2021 AE00 - 24 2022 YE60 2				
	2022 AE00 - 2				
Production Dates :	MAR 31, 2021 - F	EB 13, 2023			
VIN Range 1:	Begin :	NR	End: N	R	Not sequential
Description of Defect :					

Description of the Defect :	Buses in the recall population may allow liquid accumulation in the ESS unit that may not be detected.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	If a leak occurs inside of an ESS and is uncorrected, liquid can accumulate, leading to an electrical short, increasing the risk of a fire.
Description of the Cause :	Root-cause is unknown at this time. As inspections progress, New Flyer will analyze any ESS with liquid present and address.



Number of potentially involved :

Estimated percentage with defect :

**Population :** 

## Part 573 Safety Recall Report

Identification of Any Warning If the bus is on, warning lights on the dash would indicate an issue with a high that can Occur : voltage isolation fault.

#### **Involved Components :**

Component Name 1: NR

Component Description : NR

Component Part Number: NR

#### **Supplier Identification :**

#### **Component Manufacturer**

Name : NR Address : NR NR Country : NR

#### **Chronology** :

July, 2022, An electric bus at a customer's site was reported with a no-start condition. Prior to arrival of our Service technician, the lower rear battery enclosure was reported to be smoking, and the bus was moved outside. Ultimately, a thermal event with runaway occurred on July 27, 2022. August through October, 2022: investigation continues while reviewing data from the bus, as well as from other electric buses. The event bus's rear battery enclosures (upper and lower) were removed, quarantined, and scheduled for thorough teardown and review with multiple parties. The review of enclosure was inconclusive due to extent of damage, but internal markings indicated possible fluid collection inside the lower enclosure. November, 2022 through January, 2023: Testing and validation continued with our Service and Engineering teams.

January 18, 2023, An electric bus at a customer's site was reported with a no-start condition, and reported the lower, rear battery enclosure smoking, and the bus was moved outside. Upon our Service technician's arrival, no smoke was evident, thermal imaging showed no measurable elevation in temperature of the suspect enclosure and remained steady throughout the day. Both rear enclosures were removed from the bus and placed in a secure location. The enclosure was reviewed at the customers site the following week. Physical inspection showed internal markings that indicated possible fluid collection inside the lower enclosure. January 30th through February 8th, data analysis continues, and physical bus inspections occur. Two other enclosures were found among the buses on-site with liquid inside.

As the symptoms indicate similarity between the events, and finding of liquid, these were deemed sufficient for

The information contained in this report was submitted pursuant to 49 CFR §573

## Part 573 Safety Recall Report

formal review on February 10th, and a special Safety Committee meeting was scheduled for February 13th. The latter meeting resulted in a recall determination.				
Description of Remedy :				
Description of Remedy Program :	The remedy is currently being determined. In the interim, buses in the recall population will be inspected for liquid in the ESS units and addressed accordingly.			
	If customers have costs associated with this recall, reimbursement will occurr through New Flyer's normal warranty process.			
How Remedy Component Differs from Recalled Component :	The remedy is currently being determined.			
Identify How/When Recall Condition was Corrected in Production :	The remedy is currently being determined. Shipments of affected buses were halted.			
Recall Schedule :				
Description of Recall Schedule :	Notifications will be issued soon after approval of the Interim Draft letter.			
Planned Dealer Notification Date : Planned Owner Notification Date :	A final customer notification letter will be drafted and sent once the remedy is defined and the letter is approved. FEB 20, 2023 - FEB 20, 2023 FEB 20, 2023 <sup>-</sup> FEB 20, 2023			

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR \$573