NR

NR

Part 573 Safety Recall Report

 Manufacturer Name :
 Bombardier Recreational Products, Inc.

 Submission Date :
 MAR 20, 2023

 NHTSA Recall No. :
 23V-175

NHTSA Recall No.: 23V-175 Manufacturer Recall No.: 2023-6



Population :

23V-175

Manufacturer Information :

Manufacturer Name :Bombardier Recreational Products,
Inc.Number of potentially involved :
Estimated percentage with defect :Address :726 Saint-Joseph StreetEstimated percentage with defect :Valcourt, Quebec 00 JOE 2LO450-532-2211Estimated percentage with defect :

Vehicle Information :

	2020-2021 Can-A				
Vehicle I vne .	MOTORCYCLES	ľJ			
Body Style :					
Power Train :					
Descriptive Information :	All MY2020 and 2 of vehicles is 9 37		ed in tł	iis recall. The final quantity	y for this population
Production Dates :	SEP 18, 2019 - SE	P 27, 2021			
VIN Range 1:1	Begin :	NR	End :	NR	Not sequential
Vehicle 2:	2022-2023 Can-A	Am Ryker			
	MOTORCYCLES	5			
Body Style :					
Power Train :					
Descriptive Information :				2023 are included in this r population is 18 779.	ecall. The
Production Dates :	FEB 25, 2021 - M	AR 10, 2023			
VIN Range 1:1	Begin :	NR	End :	NR	Not sequential
Vehicle 3:	2022-2023 Can-A	Am Spyder RT			
	MOTORCYCLES	10			
Body Style :					
Power Train :	GAS				
Descriptive Information :				2023 are included in this r s populaiton is 6 299.	ecall. The
Production Dates :	NOV 10, 2021 - M	AR 10, 2023			
VIN Range 1:1	Begin :	NR	End :	NR	Not sequential

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

23V-175

Vehicle 4: 20	22-2023	Can-Am Spyde	r RT		
Vehicle Type : MO		10			
Body Style : 07					
Power Train : GA	S				
Descriptive Information : Ce		al numbers of quantity for th			
Production Dates : NO	OV 10, 202	21 - MAR 10, 20)23		
VIN Range 1 : Beg	in :	NR	End :	NR	Not sequential
-	108 - La	mps, reflective	devices, and	l assoc. Equip	ment
Description of Noncompliance	e:				
Description of the Noncompliance : EMVSS 1 :				assoc Equip	mont
FMVSS 1 : FMVSS 2 :		mps, renective	uevices, and	assoc. Equip	ment
Description of the Safety Risk :		ake lights remander			o alert other motorists of the
Description of the Cause :					the brake light switch may when the brake pedal is not
Identification of Any Warning that can Occur :	•				
Involved Components :					
Component Name 1 : E	Brake Ligh	nt Switch			
Component Description : H	brake Ligh	t Switch			
Component Part Number : N	ID				

Supplier Identification :

Component Manufacturer

Name : SMP POLAND SP. Z 0.0.

Address: 2 MAGAZYNOWA BIALYSTOK Foreign States 15-399 Country: Poland

The information contained in this report was submitted pursuant to 49 CFR §573

Chronology:

In December 2022, network status showed cases of brake lights staying on at a higher rate for MY 20222.

In trying to understand the trend, BRP made various tests and validations and looked at previous model year situation as well. BRP identified two issues:

1- Contamination on a previous brake light switch design which could induce corrosion over time and cause the brake lights to continuously illuminate. The position of the brake light switch in the vehicles is a key factor. The vehicles in this population are the MY2020 and 2021 Spyder RT.

2- The newer design of brake light switch was more resistant to contamination. However, it could have components with excessive friction for a proper brake light illumination functionality. The vehicles in this population are MY2022 and 2023 Spyder RT and MY2022 and 2023 Ryker.

With all the information collected and analyzed, BRP decided on March 9, 2023 it had enough information to report and wants to proceed with a safety recall.

No accident was reported worldwide.

Description of Remedy :

Description of Remedy Program :	 BRP will repair the vehicle at no cost. The repair will be as follows: For MY2020 and 2021 Spyder RT, the repair is to replace the brake light switch, adjust the brake light switch and add a spring to the brake light switch. For MY2022 and 2023 Spyder RT, the repair is to add a spring to the brake light switch. For MY2022 and 2023 Ryker, the repair is to adjust the brake light switch and add a spring to the brake light switch. For MY2022 and 2023 Ryker, the repair is to adjust the brake light switch and add a spring to the brake light switch. For MY2022 and 2023 Ryker, the repair is to adjust the brake light switch and add a spring to the brake light switch. The safety recall will be launched on March 17, 2023 If a customer previously had the same issue as this safety recall and BRP did not cover the cost of the repair, he/she can contact BRP for reimbursement. However, the vehicle will still need to have the safety recall repair. The General Reimbursement plan will be provided.
How Remedy Component Differs from Recalled Component :	The new brake light switch has been modified to improve its watertightness. MY2020 and 2021 Spyder RT will have this new brake light switch. Readjustment of the brake light switch to a specific torque will be completed on Spyder RT MY2020, 2021 and Ryker MY2022, 2023 A new spring to the brake light switch will be added on MY2020, 2021, 2022, 2023 Spyder RT and MY 2022, 2023 in order to allow proper activation of the brake light with the pedal.
The information	contained in this report was submitted pursuant to 49 CER §573

Page 4

	The vehicles that are still in possession of BRP will be corrected with the same remedy as per the remedy program. It is also currently planned that this will also apply for vehicles MY23 that will be produced after that date.
Recall Schedule :	
	BRP is targeting to inform dealers about this situation before the end of the day on March 17, 2023. Dealers will be instructed to contact their consumers. BRP will also send letters as soon as it will receive the updated registration information from its provider.
	the day on March 17, 2023. Dealers will be instructed to contact their consumers. BRP will also send letters as soon as it will receive the updated registration information from its provider.

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573