Manufacturer Name :	Prevost Car (US) Inc.
Submission Date :	NOV 10, 2023
<b>NHTSA Recall No. :</b>	23V-761
Manufacturer Recall No. :	SR23-42

### Manufacturer Information :

Manufacturer Name : Prevost Car (US) Inc. Address : 201 South Avenue South Plains NJ 07080 Company phone : 908-222-7211

### Vehicle Information :

Vehicle 1:	2024-2024 Prev	vost H3-45		
Vehicle Type :	BUSES, MEDIUN	M & HEAVY V	EHICLES	
Body Style :				
Power Train :	DIESEL			
Descriptive Information :	production issu manufactured of	e. The subjec luring the inc specific vehi	et vehicles are certain M dicated production date icles since they were th	action period and location as it is a IY2024 Prevost H3-45 vehicles as. The recalled products are e only ones manufactured in the
			st H3-45 vehicles are af	fected by the recall.
Production Dates :				_
VIN Range 1:	Begin :	NR	End: NR	☐ Not sequential
Vehicle 2:	2023-2024 Pre	vost H3-45 V	IP	
	BUSES, MEDIUM			
Body Style :				
Power Train :	DIESEL			
Descriptive Information :	The population was determined based on the production period and location as it is a production issue. The subject vehicles are certain MY2023 to MY2024 Prevost H3-45 VIP vehicles manufactured during the indicated production dates. The recalled products are limited to these specific vehicles since they were the only ones manufactured in the above-mentioned production period.			
	are affected by	the recall.	st H3-45 VIP, and 12 MY	(2024 Prevost H3-45 VIP vehicles
	JAN 17. 2023 - J	UL 06, 2023		
Production Dates : VIN Range 1 : 1		NR	End: NR	☐ Not sequential



Number of potentially involved : 204 Estimated percentage with defect : 25 %

**Population :** 

23V-761

	OTHER	evost X3-45 M & HEAVY VEH	IICLES		
Descriptive Information :	production iss manufactured limited to thes above-mention	ue. The subject v during the indica e specific vehicle ned production p	ehicles ated pro es since eriod.	on the production period a are certain MY2023 Prevo oduction dates. The recalled they were the only ones m	st X3-45 vehicles d products are anufactured in the
	A total of 15 M	Y2023 Prevost X	.3-45 ve	hicles are affected by the r	ecall.
Production Dates :				ND	
VIN Range 1:	Begin :	NR	End :	NR	Not sequentia
Droduction Dates	VIP vehicles m products are li manufactured A total of 4 MY affected by the	anufactured dur mited to these sp in the above-me 2023 Prevost X3 recall.	ing the i becific v ntioned	are certain MY2023 to MY2 indicated production dates ehicles since they were the production period. , and 1 MY2024 Prevost X3	s. The recalled e only ones
Production Dates : VIN Range 1 :		JUN 08, 2023 NR	E.J.		
			End :	NR	Not sequentia
			End :	NR	☐ Not sequentia

23V-761

	BUSES, MEI OTHER	Prevost X3-45 DIUM & HEAVY	VIP Entertainer VEHICLES	
Descriptive Information :	production VIP Enterta recalled pro	issue. The subj iner vehicles n oducts are limit	ect vehicles are certain MY nanufactured during the inc	tion period and location as it is 22023 to MY2024 Prevost X3-45 dicated production dates. The s since they were the only ones eriod.
			ost X3-45 VIP Entertainer, re affected by the recall.	and 29 MY2024 Prevost X3-45
Production Dates :				
VIN Range 1:	Begin :	NR	End: NR	Not sequential
FMVSS	connect overhea S 1 : NR	ed to its relay.	e grid heater cable may not This condition could cause ng the risk of a fire.	
Description of the Defe FMVSS FMVSS Description of the Safety Ri Description of the Cau Identification of Any Warr	connect overhea 5 1 : NR 5 2 : NR isk : A fire in vehicle. potentia use : During t relay ma (installa	ed to its relay. t, thus increasi creases the ris A fire may also I hazards, whic he vehicle man ay not have bee tion error). cases, a malfu	This condition could cause ng the risk of a fire. k of injury to vehicle occup require a passenger evacu ch increases the risk of inju	the cable or the relay to ants and persons around the lation in traffic and other ry. ag the grid heater cable to its revost assembly line
Description of the Defe FMVSS FMVSS Description of the Safety Ri Description of the Cau Identification of Any Warr	connect overhea 51: NR 52: NR isk: A fire in vehicle. potentia ise: During t relay ma (installa	ed to its relay. t, thus increasi creases the ris A fire may also I hazards, whic he vehicle man ay not have bee tion error). cases, a malfu	This condition could cause ng the risk of a fire. k of injury to vehicle occup require a passenger evacu ch increases the risk of inju nufacturing, the nut securin en adequately torqued by P	the cable or the relay to ants and persons around the lation in traffic and other ry. ag the grid heater cable to its revost assembly line
Description of the Defe FMVSS FMVSS Description of the Safety Ri Description of the Cau Identification of Any Warr that can Occ	connect overhea S 1 : NR S 2 : NR isk : A fire in vehicle. potentia use : During t relay ma (installa ning In some cur : instrum	ed to its relay. t, thus increasi creases the rist A fire may also Il hazards, which the vehicle man ay not have been tion error). cases, a malfut ent panel.	This condition could cause ng the risk of a fire. k of injury to vehicle occup require a passenger evacu ch increases the risk of inju nufacturing, the nut securin en adequately torqued by P nction telltale light might il	the cable or the relay to ants and persons around the lation in traffic and other ry. ag the grid heater cable to its revost assembly line
Description of the Defe FMVSS FMVSS Description of the Safety Ri Description of the Cau Identification of Any Warr that can Occ nvolved Components :	connect overhea S 1 : NR S 2 : NR isk : A fire in vehicle. potentia use : During t relay ma (installa ning In some cur : instrum	ed to its relay. t, thus increasi Creases the rist A fire may also Il hazards, which the vehicle man ay not have been tion error). cases, a malfur ent panel.	This condition could cause ng the risk of a fire. k of injury to vehicle occup o require a passenger evacu ch increases the risk of inju nufacturing, the nut securin en adequately torqued by P nction telltale light might il	the cable or the relay to ants and persons around the lation in traffic and other ry. ag the grid heater cable to its revost assembly line

The information contained in this report was submitted pursuant to 49 CFR \$573

Component Name 2 :Cable Heater Element RelayComponent Description :Cable Heater Element RelayComponent Part Number :060872

Component Name 3 : Relay Power Component Description : Relay Power Component Part Number : 563348

#### **Supplier Identification :**

#### **Component Manufacturer**

Name : NR Address : NR NR Country : NR

#### Chronology :

2023-09-25 Issue identified in production during an internal Prevost audit.

2023-09-25 Internal Prevost investigation was opened to identify the root cause and to determine if the issue is safety related.

2023-09-25 Delivery Stop was issued to stop the delivery of vehicles until the investigation is completed and corrective actions are implemented.

2023-09-28 Internal campaign was launched to solve the issue on all vehicles in production before being delivered.

2023-10-03 Case was presented on Volvo Product Safety Evaluation Committee (PSEC) to evaluate if there is a potential safety-related issue. It was concluded that further investigation was required to complete the evaluation.

2023-10-17 Case was presented on Volvo Product Safety Evaluation Committee (PSEC) to evaluate if there is a potential safety-related issue. It was concluded that further investigation was required to complete the evaluation.

2023-10-31 Case was presented on Volvo Product Safety Evaluation Committee (PSEC) to evaluate if there is a potential safety-related issue. Decision made to raise the potential safety issue to Volvo Product Safety

The information contained in this report was submitted pursuant to 49 CFR §573

23V-761

23V-761

Page 5

Committee (PSC) for review and determination.

2023-11-06 Case was presented to Volvo Product Safety Committee (PSC). It was concluded that there was a safety-related issue and that a recall is needed.

2023-11-10 Defect Information Report submitted to authorities.

No warranty claims related to this issue. No field reports, incidents, accidents, injury, or fatality were reported.

#### **Description of Remedy :**

Description of Remedy Program :	Prevost will inspect and, if required, replace any damaged components and adequately torque the grid heater relay nut on all potentially affected vehicles. Letters will be sent to customers to inform them on how to proceed. Prevost will execute this correction free of charge (parts and labor) for the customers. In case a customer has already inspected and corrected this defect before the safety recall has been launched, this customer will be reimbursed according to Prevost reimbursement plan.
<b>J</b>	The issue concerns an inadequately installed component, and not a defective component. After the remedy, the nut securing the grid heater cable on its relay will be adequately torqued.
	The recall condition was corrected in production on September 28, 2023, when an internal campaign was launched. All vehicles are corrected prior to delivery.

### **Recall Schedule :**

Description of Recall Schedule :	Please note that Prevost does not have a dealer network and the dates entered for the planned dealer notification begin/end date are only to avoid NHTSA Recall Portal error while submitting the recall report.
Planned Dealer Notification Date :	DEC 29, 2023 - DEC 29, 2023
Planned Owner Notification Date :	DEC 29, 2023 - DEC 29, 2023

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573