OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

# 24E-030

**Manufacturer Name:** Eberspaecher Climate Cntrl Syst Intl

**Submission Date:** MAR 27, 2024 NHTSA Recall No.: 24E-030 Manufacturer Recall No.: NR



#### **Manufacturer Information:**

Manufacturer Name: Eberspaecher Climate Cntrl Syst Intl

Address: Ebersp?cherstra?e 24

73730 Esslingen Esslingen 00 73730

Company phone: 508-901-1013

# **Population:**

Number of potentially involved: Estimated percentage with defect: 100 %

### **Equipment Information:**

Brand / Trade 1: Eberspächer

Model: Hydronic L-II

Part No.: HL2-16/24/30/35

Size: 600mm x ~250mm x 230mm

**Function**: Heating

Descriptive Information: The equipment recalled is the Eberspächer Hydronic L-II heaters (16-35 KW)

produced from May 1, 2023 (week 18/year 2023) to January 31, 2024 (week 5/

year 2024).

How remedy component differs from recalled component: Each

Eberspächer Hydronic L-II heater contains a type plate with the following details

that make the recall population easily distinguishable: version, reference

number, serial number, and production date (which indicates the calendar week

and year).

Identify How/When Recall Condition was Corrected in Production: All affected units produced from May 1, 2023 (week 18/year 2023) to January 31, 2024 (week 5/year 2024) will be recalibrated as needed. For all productions after January 31, 2024 (week 5/year 2024), the company has implemented a new

process that remedies the issue.

Production Dates: MAY 01, 2023 - JAN 31, 2024

#### **Description of Defect:**

Description of the Defect: The burner units of Eberspächer Hydronic L-II heaters (16-35 KW) produced

from May 1, 2023 (week 18/year 2023) to January 31, 2024 (week 5/year

2024) may have excessive exhaust gas values due to a factory calibration error.

FMVSS 1: NR FMVSS 2: NR Description of the Safety Risk: People in the immediate vicinity of these heaters could suffer smoke

inhalation due to the exhaust fumes. Furthermore, the possibility of a vehicle

fire due to increased temperatures cannot be ruled out.

Description of the Cause: NR

Identification of Any Warning NR

that can Occur:

# **Involved Components:**

Component Name: NR
Component Description: NR

Component Part Number: NR

## **Supplier Identification:**

# **Component Manufacturer**

Name: NR

Address: NR

NR

Country: NR

#### **Chronology:**

NR

### **Description of Remedy:**

Description of Remedy Program: NR

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR was Corrected in Production:

#### **Recall Schedule:**

Description of Recall Schedule: NR

Planned Dealer Notification Date : NR - NR Planned Owner Notification Date : NR - NR

#### **Purchaser Information:**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name: NR

Address: NR

NR

Country: NR

Company Phone: NR

<sup>\*</sup> NR - Not Reported