OMB Control No.: 2127-0004

Part 573 Safety Recall Report

24E-056

Manufacturer Name: Reyco Granning
Submission Date: JUL 02, 2024
NHTSA Recall No.: 24E-056



Manufacturer Information:

Manufacturer Recall No.: NR

Manufacturer Name: Reyco Granning

Address: 1205 Industrial Park Drive

Mt. Vernon MO 65712

Company phone: 4662178

Population:

Number of potentially involved : 58 Estimated percentage with defect : 10%

Equipment Information:

Brand / Trade 1: Reyco Granning / FT IFS

Model: IFS20FT, IFS22FT, IFS24FT

Part No.: 710244-01

Size: HHB 7/8-9 x 9 Gr9

Function: LCA Retention

Descriptive Information: Defect occurred in a single lot of bolts. The earliest delivery of the bolts is

associated with the beginning of the population and the end of the population

coincides with the last unit made at the time of discovery.

Non-conforming products are Marked "HK" on the head of the fastener. Products within the time frame that are not part of the population are are marked with

"FNL" or "L".

 $58\ units$ have been identified via images taken at the time of manufacture.

Production Dates: JUL 10, 2023 - APR 23, 2024

Description of Defect:

Description of the Defect: The independent front suspension (IFS) assembly was built with four bolts that

may exhibit hydrogen embrittlement. There is a resulting potential for the heads of these bolts to pop off during alignment or retorque procedures. This may result in separation of the fastener head at a high velocity which could cause injury to any persons in the vicinity when the separation occurs.

FMVSS 1: NR FMVSS 2: NR Description of the Safety Risk: In the case where the listed defect results in a failure of the bolt, separation of

the fastener head from the main bolt body can result in injury.

Description of the Cause: Bolts were stripped of their original coating and re-plated with zinc, resulting

in hydrogen embrittlement within a portion of the affected bolt lot.

Identification of Any Warning If hydrogen embrittlement is present within a fastener and the joint is re-

that can Occur: torqued during an alignment where joint clamp load is higher than that

produced during original assembly, the fastener head could separate from the

main bolt body without warning.

Involved Components:

Component Name: LCA to cradle mounting hardware

Component Description: HHB 7/8-9 X 9 9 ZN

Component Part Number: 710244-01

Supplier Identification:

Component Manufacturer

Name: Fastenal

Address: 2001 Theurer Blvd.

Winona Minnesota 55987

Country: United States

Chronology:

Initial bolt failure - March 6th 2024 Bolt repaired at the time. Over the course of the next month 2 more failed. April 24th Spartan motors discussed issue with their Fastenal rep. It was noted by the Fastenal representative that there was the possibility of hydrogen embrittlement. Parts sent for testing by Fastenal. Reyco sent parts for testing on March 27 (third party) quote received 4/18/2024 parts sent for testing. Test report received (Third party) 5/2/2024 noting failed parts did have hydrogen embrittlement. Normally, parts with HE fail within 24 to 48 hours - no trucks that had been sitting failed in that time frame. Testing was done to determine why certain trucks failed outside of this window, It was determined that the failures only occurred post alignment activity where torques higher than the original installation torque were achieved. Decision to move forward with recall was based on discussions between Spartan Fire and Reyco, where a concern was raised regarding safety of the individual(s) under the vehicle, during alignment procedures. Decision to move forward was finalized week of June 24th.

Description of Remedy:

Description of Remedy Program: Target population has been defined down to the individual serial numbers. This was accomplished by reviewing images of the FT IFS units produced (Pictures are taken as part of the normal QC activities surrounding the build up of Reyco IFS units). Serial numbers for units with "HK" bolt head marking were identified. A TSB has been created that defines the bolt replacement process, including marking methodologies etc. that need to be employed so that vehicle alignment remains unaffected. Removal of bolts is not an safety issue as failure only occurs post tightening of the fasteners.

> Reyco will be writing letters to each of the manufacturers listed that used the product describing the issue etc. A copy of the TSB will be sent as well. 2 hours will be allowed for labor, bolt kits will be offered at no charge with a token "tracking fee" any additional fees and labor rates will be negotiated with each of the manufacturers involved. A reserve account has been set up to cover costs.

How Remedy Component Differs All fasteners marked with an "HK" on the head are suspect (Not all are from Recalled Component: bad). If they were built within the timeframe described and they have the "HK" marking the fasteners will be replaced with fasteners marked with "L9". (HK fasteners were stripped and re-plated, "L9" fasteners went through the normal manufacturing process).

Identify How/When Recall Condition On 4/23/2024 all HK bolts were quarantined and removed from was Corrected in Production: production. Fastenal delivered brand "L9" marked fasteners that day that were immediately used in production.

Recall Schedule:

Description of Recall Schedule: Letters will be written the week of July 8th and will go out shortly

thereafter. Note we will be notifying the Chassis Manufacturers above.

Planned Dealer Notification Date: JUL 08. 2024 - JUL 19. 2024

Planned Owner Notification Date: NR - NR

Purchaser Information:

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name: Spartan Fire LLC

Address: 1541 Reynolds Road

Charlotte MI 48813

Country: US

Company Phone: 5175884136

Name: E-One

Address: 3611 SW 20th Street

Ocala FL 34474

Country: US

Company Phone: 3525728518

Name: HME

Address: 1950 Byron Center Ave SW

Wyoming MI 49519

Country: US

Company Phone: 6165341463

Name: Rosenbauer Motors LLC

Address: 5190 260th St

Wyoming MN 55092

Country: US

Company Phone: 6514621000

Name: Metro Fire Apparatus Specialist

Address: 17350 Tomball Pkwy

Houston TX 77064

Country: US

Company Phone: 7136920911

^{*} NR - Not Reported