Part 573 Safety Recall Report

Manufacturer Name :Multiquip, Inc.Submission Date :OCT 18, 2024NHTSA Recall No. :24V-768Manufacturer Recall No. :TL20160921

Manufacturer Information :

Manufacturer Name : Multiquip, Inc. Address : 6141 Katella Avenue, Suite 200 PO Box 6002 Cypress CA 90630

Company phone : 800-421-1244

Vehicle Information :

Vehicle 1:	2012-2015 Multiquip TRLR-55164				
Vehicle Type :	TRAILERS				
Body Style :					
Power Train :	NR				
Descriptive Information :	 -Recall population determined by matching failure reports to corresponding production months and 2016 change in manufacturing staff - Recalled products may not have undergone beveling process, which makes welds on trailer frame prone to cracking. - 4 units affected in this range. 				
Production Dates :	JAN 01, 2012 - DEC 31, 2015				
VIN Range 1 : Begin : 5SLBG1520CL009508 End : 5SLBG1527FL017660 Vin sequential					
Vehicle 2 : Vehicle Type : Body Style : Power Train :					
Descriptive Information :	 -Recall population determined by matching failure reports to corresponding production months and 2016 change in manufacturing staff - Recalled products may not have undergone beveling process, which makes welds on trailer frame prone to cracking. - 85 units affected in this range. 				
Production Dates :	JAN 01, 2010 - JUN 01, 2016				
VIN Range 1 : Begin : 5SLBG1428AL005382 End : 5SLBG1420GL018734 Not sequential					
VIN Range 1:	Begin : 5SLBG1428AL005382 End : 5SLBG1420GL018734 ✓ Not sequential				



Number of potentially involved :

Estimated percentage with defect : 11%

Population :

92

24V-768

Part 573 Safety Recall Report

Vehicle 3: 2	013-2013 Multiquip TRLR-57615				
Vehicle Type : TRAILERS					
Body Style :					
Power Train : N	R				
Descriptive Information : -Recall population determined by matching failure reports to corresponding production months and 2016 change in manufacturing staff - Recalled products may not have undergone beveling process, which makes welds on trailer frame prone to cracking. - 3 units affected in this range.					
Production Dates : JA	AN 01, 2013 - DEC 31, 2013				
U	gin: 5SLBG1428DR012981 End: 5SLBG1428DR012981 Not sequential				
VIN Range 2 : Be	gin: 5SLBG1429DR013556 End: 5SLBG1420DR013557 Not sequential				
-	An important beveling process may not have been performed during manufacturing of studio trailer frame weldments. As a result, the frames may be subject to cracking at the top and bottom of the tubes				
-	manufacturing of studio trailer frame weldments. As a result, the frames may be subject to cracking at the top and bottom of the tubes.NR				
Description of the Defect FMVSS 1 FMVSS 2 Description of the Safety Risk	 manufacturing of studio trailer frame weldments. As a result, the frames may be subject to cracking at the top and bottom of the tubes. NR NR Failing welds may lead to sudden collapse of the trailer frame, leading to loss of control and debris left on the road. These problems increase risk of crash. 				
Description of the Defect FMVSS 1 FMVSS 2 Description of the Safety Risk Description of the Cause	 manufacturing of studio trailer frame weldments. As a result, the frames may be subject to cracking at the top and bottom of the tubes. NR NR Failing welds may lead to sudden collapse of the trailer frame, leading to loss of control and debris left on the road. These problems increase risk of crash. Some trailers did not undergo beveling process 				
Description of the Defect FMVSS 1 FMVSS 2 Description of the Safety Risk Description of the Cause	 manufacturing of studio trailer frame weldments. As a result, the frames may be subject to cracking at the top and bottom of the tubes. NR NR Failing welds may lead to sudden collapse of the trailer frame, leading to loss of control and debris left on the road. These problems increase risk of crash. Some trailers did not undergo beveling process Cracking of welds on joints of trailer frame. Visible sagging of trailer frame. 				
Description of the Defect FMVSS 1 FMVSS 2 Description of the Safety Risk Description of the Cause Identification of Any Warning that can Occur	 manufacturing of studio trailer frame weldments. As a result, the frames may be subject to cracking at the top and bottom of the tubes. NR NR Failing welds may lead to sudden collapse of the trailer frame, leading to loss of control and debris left on the road. These problems increase risk of crash. Some trailers did not undergo beveling process Cracking of welds on joints of trailer frame. Visible sagging of trailer frame. 				
Description of the Defect FMVSS 1 FMVSS 2 Description of the Safety Risk Description of the Cause Identification of Any Warning that can Occur	 manufacturing of studio trailer frame weldments. As a result, the frames may be subject to cracking at the top and bottom of the tubes. NR NR Failing welds may lead to sudden collapse of the trailer frame, leading to loss of control and debris left on the road. These problems increase risk of crash. Some trailers did not undergo beveling process Cracking of welds on joints of trailer frame. Visible sagging of trailer frame. 				
FMVSS 1 FMVSS 2 Description of the Safety Risk Description of the Cause Identification of Any Warning that can Occur	manufacturing of studio trailer frame weldments. As a result, the frames may be subject to cracking at the top and bottom of the tubes. NR NR Failing welds may lead to sudden collapse of the trailer frame, leading to loss of control and debris left on the road. These problems increase risk of crash. Some trailers did not undergo beveling process Cracking of welds on joints of trailer frame. Visible sagging of trailer frame.				

Supplier Identification :

Component Manufacturer

Name: NR

The information contained in this report was submitted pursuant to 49 CFR $\S573$

Part 573 Safety Re	24V-768	Page 3	
Address : NR NR Country : NR			
Chronology : 5/26/2016 - Multiquip is informed of 10/07/16 - Multiquip begins service issued to equipment owners, alertin 8/29/2024 - During discussion with reported as a safety recall 10/09/2024 - NHTSA staff instructs	e bulletin campaign to customers g them of the need to have an ins NHTSA staff it is brought to Mul	s of affected units: A series of mailin spection and repair completed. Itiquip's attention that this defect w	C
Description of Remedy :			
Description of Remedy Program :	initially reported. Multiquip ma order repair parts - free of char allowance for the complete repa	s conducted in 2016, when the defe ailed instruction to inspect affected ge, and provided trailer owners a la air. Trailer owners were not charg costs. Of the 92 units, 81 were mark solved.	trailers, abor ed for
	owners of the remaining 11 uni	safety recall notices to the last know its, providing parts and labor to tra hat completed this remedy prior to	iler
		have two inner reinforcement plate he a-frame, where cracking may occ es is EE59670.	
Identify How/When Recall Condition was Corrected in Production :	Additional training was provide longer in production in 2024.	ed to production crew. This trailer	is no
Recall Schedule :			
	5	will be sent to the last known owne rterly basis. Our safety recall notic NHTSA standards.	
Planned Dealer Notification Date : Planned Owner Notification Date :	direct customers of Multiquip. NR - NR	this recall. The last known owners	are

The information contained in this report was submitted pursuant to 49 CFR \$573

Part 573 Safety Recall Report

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573