Part 573 Safety Recall Report

Manufacturer Name :	Mercedes-Benz USA, LLC
Submission Date :	DEC 18, 2024
NHTSA Recall No. :	24V-941
Manufacturer Recall No. :	NR

Manufacturer Information :

Vehicle Information :

Manufacturer Name :	Mercedes-Benz USA, LLC
Address :	13470 International Parkway
	Jacksonville FL 32218
Company phone :	1-877-496-3691

Population :

Number of potentially involved : 17 Estimated percentage with defect : 100 %

Vehicle 1:	2025-2025 N	lercedes-Ben	z E 350			
Vehicle Type :	LIGHT VEHIC	CLES				
Body Style :	4-DOOR					
Power Train :	GAS					
Descriptive Information :	determined t	hrough produ	uction record	ls. Vehicle	e. The recall popu es outside of the r ction specificatior	ecall population
Production Dates :	AUG 12, 2024	4 - SEP 06, 202	24			
VIN Range 1:	Begin :	NR	End :	NR		Not sequential
Vehicle 2 : Vehicle Type : Body Style : Power Train : Descriptive Information :	4-DOOR GAS Mercedes Be determined t	CLES nz Model Yea hrough produ	r 2025 E 350 action record) 4MATIC ls. Vehicle	8 Vehicles. The rees outside of the rection specification	ecall population
Production Dates :	AUG 12, 2024	4 - SEP 06, 202	24			
VIN Range 1:	Begin :	NR	End :	NR		□ Not sequential



NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

24V-941

Part 573 Safety Recall Report

24V-941

Vehicle 3: 2	025-2025 Mercedes	s-Benz E 450 4MA	TIC		
Vehicle Type : L					
Body Style : 4					
Power Train : G					
Descriptive Information : M	lercedes Benz Mode	production record	ls. Vehicles outsid	es. The recall population was e of the recall population cifications.	
Production Dates : A	UG 12, 2024 - SEP 0	6, 2024			
VIN Range 1 : Be	gin: NR	End :	NR	☐ Not sequential	
Vehicle Type : L	FATIONWAGON	s-Benz E 450 4MA	TIC Station Wagoı	n	
	opulation was deter	mined through pr	roduction records.	Wagon 4 Vehicles. The recall . Vehicles outside of the recal duction specifications.	
Production Dates : A			ND		
Production Dates : A VIN Range 1 : Be			NR	☐ Not sequential	
VIN Range 1 : Be	gin : NR Mercedes-Benz A determined that o vehicles, the welc	End : G ("MBAG"), the n on certain Model Y s for the camber s	nanufacturer of Mo 'ear ("MY") 2025 I strut brackets to th	□ Not sequential ercedes-Benz vehicles, has E-Class (214 platform) he rear axle carrier might	
VIN Range 1 : Be	gin : NR Mercedes-Benz A determined that ovehicles, the welch not meet current	End : G ("MBAG"), the n on certain Model Y s for the camber s	nanufacturer of Mo 'ear ("MY") 2025 I strut brackets to th	ercedes-Benz vehicles, has E-Class (214 platform)	
VIN Range 1 : Be Description of Defect : Description of the Defect :	gin : NR Mercedes-Benz A determined that of vehicles, the weld not meet current NR	End : G ("MBAG"), the n on certain Model Y s for the camber s	nanufacturer of Mo 'ear ("MY") 2025 I strut brackets to th	ercedes-Benz vehicles, has E-Class (214 platform)	
VIN Range 1 : Be Description of Defect : Description of the Defect : FMVSS 1 :	gin : NR Mercedes-Benz A determined that of vehicles, the weld not meet current NR NR If the welds for the the weld might no detach from the r	End : G ("MBAG"), the m on certain Model Y is for the camber s production specifient e camber strut br ot withstand the for ear axle carrier with	nanufacturer of Mo Year ("MY") 2025 I strut brackets to th ications. ackets to the rear prces while driving ithout warning. As	ercedes-Benz vehicles, has E-Class (214 platform) he rear axle carrier might axle carrier are affected, g and the bracket might	
VIN Range 1 : Be Description of Defect : Description of the Defect : FMVSS 1 : FMVSS 2 :	gin : NR Mercedes-Benz A determined that of vehicles, the weld not meet current NR NR If the welds for th the weld might no detach from the r guidance and driv risk of a crash. Due to a deviation	End : G ("MBAG"), the m on certain Model Y is for the camber s production specifient of withstand the for ear axle carrier with ving stability might n in the production	nanufacturer of Mo Year ("MY") 2025 I strut brackets to th ications. ackets to the rear prces while driving ithout warning. As t be impaired, wh	ercedes-Benz vehicles, has E-Class (214 platform) he rear axle carrier might axle carrier are affected, g and the bracket might s a result, wheel ich could increase the ds of certain rear axle	

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

24V-941

Component Name 1 :Rear Axle CarrierComponent Description :Rear Axle CarrierComponent Part Number :A2063509707

Supplier Identification :

Component Manufacturer

Name : MBAG Address : NR NR Country : NR

Chronology :

On December 9, 2024, MBAG launched initial investigations based on an internal report from one of its assembly plants. This report indicated an incorrectly executed weld of a camber strut bracket to the rear axle carrier. These investigations determined a deviation in the production process of a certain batch of rear axle carriers, which were produced outside of the vehicle production plant, in July and August 2024. Subsequently, potential consequences on the vehicles in the field were analyzed and the potentially affected vehicles were identified.

On December 13, 2024, MBAG determined that a potential safety risk cannot be ruled out and decided to conduct a recall.

MBAG can confirm there are no warranty claims, field or service reports, and other information related to this defect worldwide.

The information contained in this report was submitted pursuant to 49 CFR §573

Description of Remedy :

: An authorized Mercedes-Benz dealer will replace the rear axle carrier of the affected vehicles.	
Until the remedy is completed, customers will be instructed by the MBUSA Customer Care Center (CCC) not to drive their vehicle and will assist to make arrangements with their preferred Mercedes-Benz dealer to have the vehicle towed for repair. Towing and loaner vehicles, where available, will be offered at no cost to the customer.	
Pursuant to 49 C.F.R. § 577.11(e), MBUSA does not plan to provide notice about pre-notice reimbursement to owners since none of the involved vehicles would have been previously subject to the condition described and all remain covered under the new vehicle warranty.	
Vehicles outside of the recall population have rear axle carrier camber strut brackets that are welded to the proper production specifications. Remedy Part No: Rear Axle Carrier A2063509707	
A change in the production procedure ensures that this issue can no longer occur from December 3, 2024 onwards.	
MBUSA will issue a stop-drive warning notice for the vehicles affected by this recall on December 19, 2024. A copy of all communications will be provided when available. Customers will be instructed by the MBUSA Customer Care Center (CCC) not to drive their vehicle and the CCC will assist to make arrangements with their preferred Mercedes-Benz dealer to have the vehicle towed for repair. Towing and loaner vehicles or alternate transportation, where available, will be offered at no cost to the customer.	

Official owner notifications will be sent following NHTSA approval of the customer notification letter on or before February 16, 2025. A copy of all communications will be provided when available.

Planned Dealer Notification Date : DEC 19, 2024 - NR Planned Owner Notification Date : FEB 16, 2025 - NR

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR \$573