

# Part 573 Safety Recall Report

## 25V-151

**Manufacturer Name :** Keystone RV Company

**Submission Date :** MAR 11, 2025

**NHTSA Recall No. :** 25V-151

**Manufacturer Recall No. :** 25-463



### Manufacturer Information :

Manufacturer Name : Keystone RV Company

Address : PO Box 2000  
2642 Hackberry Drive Goshen IN  
46527

Company phone : 574-535-2100

### Population :

Number of potentially involved : 873

Estimated percentage with defect : 100 %

### Vehicle Information :

Vehicle 1 : 2025-2025 Dutchmen Kodiak

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : All models, Floor plans that use the 7 way cord and 12 Volt Distribution Box may be affected.

Kodiak 463 units

Production Dates : AUG 01, 2024 - FEB 19, 2025

VIN Range 1 : Begin : 4YDTKDG16SJ970291 End : 4YDTKDP29SJ970753 ☒ Not sequential

Vehicle 2 : 2025-2025 Dutchmen Colorado 260RBC, 270BHC, 280BHC

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Floor plans that use the 7 way cord and 12 Volt Distribution Box may be affected.  
Colorado units 37

Production Dates : SEP 06, 2024 - FEB 17, 2025

VIN Range 1 : Begin : 4YDTC0N21SJ950216 End : 4YDTC0M2XSJ950623 ☒ Not sequential

Vehicle 3 : 2025-2025 CrossRoads Sunset  
Vehicle Type : TRAILERS  
Body Style :  
Power Train : NR

Descriptive Information : Floor plans that use the 7 way cord and 12 Volt Distribution Box may be affected.  
Sunset units 373

Production Dates : AUG 05, 2024 - FEB 04, 2025  
VIN Range 1 : Begin : 4YDTSSM23SJ350005 End : 4YDTSSN2XSJ350373 ☒ Not sequential

Description of Defect :

Description of the Defect : It has been decided that the vehicles in the recall population have been wired incorrectly at the 7-way cord and 12 Volt Distribution Box.  
FMVSS 1 : NR  
FMVSS 2 : NR  
Description of the Safety Risk : Under certain conditions during travel, the charge line may not be properly protected leading to an increased risk of fire.  
Description of the Cause : The wiring may be incorrect at the 7-way cord and 12 Volt Distribution Box  
Identification of Any Warning that can Occur : Fuses may blow causing slide outs not to operate.

Involved Components :

Component Name 1 : Box 12v Power Distribution TT  
Component Description : Box - 12v Power Distribution - TT - w/8' 7-Way Cord, 5 Breakers (30S/30S/50/30/30) & 150 Amp Battery Disconnect  
Component Part Number : 749671

Supplier Identification :

Component Manufacturer

Name : NR  
Address : NR  
NR

Country : NR

Chronology :

- 2/18/2025 – Report was made.
- 2/18/2025 – Investigation opened. All affected units not shipped were put on hold and inspected and repaired in the yard.
- 2/18/2025 – There are no warranty claims for this issue at this time.
- 3/3/2025 – Keystone Safety Committee reviewed the information and concluded that the data reviewed indicated a unanimous vote for a voluntary recall. Investigation called for to determine affected unit range.
- 3/6/2025 – Investigation concluded and scope completed.

Description of Remedy :

Description of Remedy Program :	The remedy is to repair affected wiring using included diagram and images. Manufacturer Reimbursement Plan on file as of 10/3/2024. General reimbursement plan to be updated every two years. New vehicles are covered under warranty.
How Remedy Component Differs from Recalled Component :	No parts will be replaced. The repair is to move the affected wires to the correct location.
Identify How/When Recall Condition was Corrected in Production :	Units were quarantined, inspected, then repaired as indicated by inspection.

Recall Schedule :

Description of Recall Schedule :	Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.
Planned Dealer Notification Date :	APR 28, 2025 - APR 28, 2025
Planned Owner Notification Date :	APR 28, 2025 - APR 28, 2025

\* NR - Not Reported