

# Part 573 Safety Recall Report

# 25V-152

**Manufacturer Name :** Shyft Group

**Submission Date :** MAR 11, 2025

**NHTSA Recall No. :** 25V-152

**Manufacturer Recall No. :** 25-07



## Manufacturer Information :

**Manufacturer Name :** Shyft Group

**Address :** 1541 Reynolds Road  
Charlotte MI 48813

**Company phone :** 517-543-6400

## Population :

**Number of potentially involved :** 605

**Estimated percentage with defect :** 100 %

## Vehicle Information :

**Vehicle 1 :** 2025-2025 Utilmaster Upfit

**Vehicle Type :** LIGHT VEHICLES

**Body Style :** OTHER

**Power Train :** HYBRID ELECTRIC

**Descriptive Information :** The recall population was determined by using production and personnel records to identify a change in personnel within the work center where the jump seat installation occurs.

**Production Dates :** JAN 16, 2025 - FEB 27, 2025

**VIN Range 1 :** Begin : 1FTBW9CK0RKB77786 **End :** 1FTBW9CK9SKA10235  Not sequential

## Description of Defect :

**Description of the Defect :** The fold up jump seat mounting fasteners may have been improperly torqued.

**FMVSS 1 :** 207 - Seating systems

**FMVSS 2 :** NR

**Description of the Safety Risk :** Improperly torqued jump seat mounting fasteners may fail during a crash causing the jump seat to move which could increase the risk of occupant injury.

**Description of the Cause :** Change in personnel within the work center where jump seats are installed.

**Identification of Any Warning that can Occur :** A jump seat mounting fastener may fail without warning.

## Involved Components :

Component Name 1 : Flip-up Jump Seat

Component Description : Passenger Jump Seat

Component Part Number : NR

## Supplier Identification :

### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

## Chronology :

On March 6, 2025, concern with improper torque for the jump seat mounting fasteners was raised to Product Safety and Compliance. On March 7, 2025 the problem was reviewed in more detail including the potential scope of the problem. On March 11, 2025 The Shyft Group, Inc. determined the problem could result in a non-compliance to Federal Motor Vehicle Safety Standard No. 207.

## Description of Remedy :

Description of Remedy Program : The jump seat mounting fasteners will be inspected for proper torque and if necessary, tightened to the appropriate value. All vehicles subject to this recall are within their upfit warranty period. Although we are not aware of any complaints/claims involving failed jump seat mounting fasteners, any claim would have been paid through normal course at no charge to the customer.

How Remedy Component Differs from Recalled Component : The jump seat mounting fasteners will be marked with a contrasting color from other marks on the fasteners indicating proper torque.

Identify How/When Recall Condition was Corrected in Production : The issue was identified in production during a routine calibration audit. Once identified, use of the appropriate, calibrated tool was reimplemented with new operations personnel.

## Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : MAR 11, 2025 - MAR 17, 2025

Planned Owner Notification Date : MAR 17, 2025 - MAR 21, 2025

\* NR - Not Reported