



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V333

Manufacturer Name: Mack Trucks, Inc.

Submission Date: May 21, 2025

NHTSA Recall No.: 25V333

Manufacturer Recall No.: SC0478

Manufacturer Information

Population

Manufacturer Name: Mack Trucks, Inc.

Address: 2100 Mack Boulevard
PO Box M
Allentown PA, 18105-5000

Total number of potentially involved: 42

Estimated percentage with defect: 21.4%

Vehicle Information

Vehicle 1: 2025-2025 MACK MD

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Truck

Fuel / Propulsion: Compression Ignition Fuel

Production Dates: Mar 22, 2025 - Apr 08, 2025

Number of potentially involved: 42

Descriptive Information:

Certain Mack MD trucks built with a specific seatbelt part number as identified by the seat belt manufacturer. Mack, MD, MY2026

Defect / Noncompliance Description

Description of the defect or noncompliance:

Certain Mack MD built with seatbelts where the belt routing is incorrect on the tongue (latch plate) assembly. This would prevent the seat belt from performing correctly.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

In the event of a crash, the incorrectly routed seatbelt would not perform as designed and this could increase the risk of an injury.

Part 573 Safety Recall Report

25V333

Description of the cause:

Assembled by the supplier incorrectly.

Identification of any warning that can occur:

There are no warnings associated with this.

Component Manufacturer

Tier of Supplier: Tier 1

Supplier Type: OEM

Name: IMMI Inc.

Address: 18881 IMMI Way
Westfield IN, 46074

Country: United States

Involved Components

Component Name 1: Seat Belt

Component Description: Black Bench

Component Part Number: 24732721

Chronology

April 23, 2025 Mack Assembly Operations identifies an issue with the center seatbelt for bench seat not routed properly and starts containment and contacts supplier of the concern.

April 24, 2025 Product Safety Evaluation is notified of the potential issue and a product safety investigation is opened.

May 5, 2025 Product Safety Evaluation Committee meets and reviews the findings from manufacturing and the supplier and recommends that this be escalated to Product Safety Committee as a potential product safety defect .

May 14 , 2025 Product Safety Committee meets and determines that a safety defect exists and a recall will be conducted.

May 21 , 2025 Product safety defect 573/DIR filed with NHTSA.

There has been no warranty claims, field reports, accidents or injuries reported with this issue.

Related NHTSA Recall Number:

Part 573 Safety Recall Report

25V333

Description of Remedy

Remedy Type: Inspect, Replace**Consumer Advisories:** ☐ Do Not Drive ☐ Park Outside**Description of remedy program:**

Vehicles will be recalled and the seatbelt assembly will inspected for proper routing replaced as necessary.

How remedy component differs from recalled component:

The seatbelt will have the belt routed correctly on the tongue (latch plate) assembly which ensures the belt operates as designed. 24732721 Seat Belt, Black Bench.

Identify how/when recall condition was corrected in production:

Any vehicles under our control which were impacted were put on hold and corrected. April 24, 2025

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Dealer notification will begin on or before May 26, 2025 and owner notification will begin on or before July 18, 2025

Planned Dealer Notification Date: May 26, 2025 - May 26, 2025 ☐ No Dealers

Planned Interim Owner Notification Date: ☐ No Owners

Planned Remedy Owner Notification Date: Jul 18, 2025 - Jul 18, 2025 ☐ Phased Recall

Date when VIN will be searchable: May 26, 2025