



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

25V534

Manufacturer Name: International Motors, LLC

Submission Date: Aug 21, 2025

NHTSA Recall No.: 25V534

Manufacturer Recall No.: 25513

Manufacturer Information

Population

Manufacturer Name: International Motors, LLC

Address: 2701 Navistar Drive
Lisle IL, 60532

Total number of potentially involved: 1,175

Estimated percentage with defect: 1%

Vehicle Information

Vehicle 1: 2026-2026 INTERNATIONAL MV

Product Category: Buses, Medium & Heavy Vehicles

Product Type:

Fuel / Propulsion:

Production Dates: Mar 01, 2025 - Jun 11, 2025

Number of potentially involved: 1,175

Descriptive Information:

The suspect population was identified by certain vehicles built 03/01/2025 thru 06/11/2025 with 25" Battery Boxes and/or feature codes listed below-

- MV models with 25" Battery Boxes (0008VUX,0008VUY,0008VUG,0008VVH,0008VUW,0008VVG)
- 2 Battery System in All Boxes with Jump Start Stud (0008WBW), which codes an auxiliary 3/8" post on the battery interconnect
- 3 Battery System in Right Side Battery Boxes (0008VUX,0008VUG, or 0008VVH) with Jump Start Stud (0008WBW)
- 3 Battery System in Left Side Battery Boxes (0008VUY,0008VUW, or 0008VVG) with Jump Start Stud (0008WBW) & PDM (0508093)
- 3 Battery System in Left Side Battery Boxes (0008VUY,0008VUW,or 0008VVG) with Disconnect Switch (0008RMH or 0008XHD)

How the recalled products differ from products that were not included in the recall

The vehicles in the suspect population were identified by their build dates and feature codes. All other similar vehicles, which are not subject to this recall, are excluded.

Part 573 Safety Recall Report

25V534

Defect / Noncompliance Description

Description of the defect or noncompliance:

Manufacturing variation can allow for contact between battery interconnect cable with auxiliary stud and hold down bracket.

FMVSS1:**FMVSS2:****Description of the safety risk, including crash, fire, death, injury:**

- When contact between these components occurs, a short circuit can develop which may generate excessive heat, which can result in a fire, increasing the risk of property damage or personal injury to the operator.

Description of the cause:**Identification of any warning that can occur:**

Component Manufacturer

Tier of Supplier:**Supplier Type:****Name:****Address:****Country:**

Involved Components

Component Name 1: CLAMP**Component Description:** BATTERY HOLD DOWN**Component Part Number:** 3553499C2**Component Name 2:** CLAMP**Component Description:** BATTERY HOLD DOWN

Part 573 Safety Recall Report

25V534

Component Part Number: 3553499C2

Chronology

05/05/2025 – International R&D and Product Integrity are notified of a thermal event at International's third-party holding facility. International initiates an investigation to review findings.

05/30/2025 – Parts analysis indicates that the damaged vehicle exhibits contact between the battery terminal and the battery hold down.

06/03/2025 – International's Product Integrity Office is notified of a thermal event reported to originate in the battery box region. International coordinates an inspection of the vehicle.

06/11/2025 – Escobedo and San Antonio Assembly Plants initiate a quality alert at final assembly, advising that the terminal is not contacting the battery hold down and establishing the clean point.

06/13/2025 – International's Product Integrity Office is notified of an additional thermal event.

06/16/2025 – San Antonio Assembly Plant performs an inspection on 187 vehicles, finding no contact between the battery terminal and battery hold down during inspection.

06/24/2025 – Product Integrity determines that the thermal event reported on 06/03/2025 had contact between the positive cable and the battery hold down.

07/09/2025 – International R&D and Product Safety meet to discuss the battery lug as a potential root cause and expand the investigation.

07/29/2025 – International R&D and the Product Safety Office meet to review the inspection of the additional thermal event reported on 06/13/2025, which exhibits contact between the positive cable and the battery hold down.

08/07/2025 – Escobedo and San Antonio Assembly Plants initiate a second quality alert, advising the use of a go-no-go gage and updating work instructions.

08/13/2025 – International finalizes the suspect population.

08/14/2025 – International declares a safety recall.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Replace

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

Install 3 wind laces on the battery hold down for insulation, add a J-bolt between each battery for spacing, and check for 3 mm terminal clearance after torquing

How remedy component differs from recalled component:

Part 573 Safety Recall Report**25V534**

Identify how/when recall condition was corrected in production:

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule**Description of recall schedule:**

- It is estimated that the dealer notification letter will be mailed by 10/6/2025.
- It is estimated that the Customer notification letter will be mailed by 10/13/2025.

Planned Dealer Notification Date:

☐ No Dealers

Planned Interim Owner Notification Date:

☐ No Owners

Planned Remedy Owner Notification Date:

☐ Phased Recall

Date when VIN will be searchable: