OMB Control No.: 2127-0004

Part 573 Safety Recall Report

19E-012

Manufacturer Name: Dana Incorporated

Submission Date: FEB 13, 2019

NHTSA Recall No.: 19E-012

Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Dana Incorporated

Address: 3939 Technology Drive

Maumee OH 43537

Company phone: 419-887-3000

Population:

Number of potentially involved: NR Estimated percentage with defect: NR

Equipment Information:

Brand / Trade 1: Dana - Spicer

Model: To be provided Part No.: To be provided

Size: NR Function: NR

Descriptive Information: The issue potentially affects certain front steer axles for aftermarket and service.

Intensive investigation is underway regarding the population.

Production Dates: OCT 13, 2018 - OCT 28, 2018

Description of Defect:

Description of the Defect: Four axles have been returned in warranty with seized tail bearing. An

intensive root cause investigation is underway.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: In the event of a pinion tail bearing seizure, the axle may not be able to rotate.

If this occurs, it could affect a vehicle operator's control of the vehicle.

Description of the Cause: Intensive root cause investigation is underway.

Identification of Any Warning Intensive investigation is underway on early warnings.

that can Occur:

Supplier Identification:

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology:

Dana got partial and inconclusive evidence of a potential issue with a front steer axle on February 5, and, immediately initiated an intensive root cause analysis. Out of an abundance of caution, Dana determined to report now as investigation continues. A more complete chronology will follow.

Description of Remedy:

Description of Remedy Program : Corrective action will turn on the fruits of the intensive Dana investigation

underway. For parts within dealer or distributor inventory, Dana would most likely provide replacement parts. For parts installed within consumer vehicles, Dana would most likely cover the cost of towing vehicles to dealers to replace parts. Corrective action may also include an element of inspection. Dana will come forward with proposed corrective

action for NHTSA's consideration.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: NR

Planned Dealer Notification Date: NR - NR Planned Owner Notification Date: NR - NR

Purchaser Information:

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Part 573 Safety Recall Report

19E-012

Page 3

Name: NR

Address: NR

NR

Country: NR

Company Phone: NR

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573