OMB Control No.: 2127-0004

Part 573 Safety Recall Report

19V-139

Manufacturer Name: Daimler Trucks North America LLC

NHTSA Recall No.: 19V-139

Manufacturer Recall No.: FL-809



Manufacturer Information:

Manufacturer Name: Daimler Trucks North America LLC

Address: 4747 N. Channel Avenue

Portland OR 97217-3849

Company phone: 800-745-8000

Population:

Number of potentially involved: 2 Estimated percentage with defect: 6 %

Vehicle Information:

Vehicle 1: 2019-2019 FCCC S2RV Chassis Cab

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: Certain chassis cab vehicles within the build range, built without ABS module

Production Dates: OCT 05, 2018 - DEC 18, 2018

Description of Noncompliance:

Description of the On the affected chassis cab vehicles, the ABS modules may not have been

Noncompliance: installed as required by FMVSS 121 S5.1.6.

FMVSS 1: 121 - Air brake systems

FMVSS 2: NR

Description of the Safety Risk: The operator may not be aware of the absence of ABS function. Unknowingly

operating the vehicle without ABS function may increase risk of a crash.

Description of the Cause: NR

Identification of Any Warning NR

that can Occur:

Supplier Identification:

Component Manufacturer

Name: NR Address: NR NR Country: NR

Chronology:

On January 7th, 2019 Freightliner Custom Chassis was advised by our transporting contractor of ABS lamp malfunction due to ABS module omission, while completed vehicles were being transferred from our plant to the customers. DTNA began investigation to understand scope of issue. Early February 2019 DTNA began field inspection of vehicles within the impacted population exposure. February 2019, with an abundance of caution, DTNA decided to initiate a voluntary recall.

Description of Remedy:

Description of Remedy Program: Cab Chassis Vehicles will be inspected and ABS module will be installed

where necessary. Repairs will be performed by Daimler Trucks North America authorized service facilities. Copies of the reimbursement plan

will be submitted as a supplemental report when available.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: Customer notification will be made by first class mail using Daimler

Trucks North America records to determine the customers affected.

Planned Dealer Notification Date: APR 27, 2019 - APR 27, 2019 Planned Owner Notification Date: APR 27, 2019 - APR 27, 2019

* NR - Not Reported