OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

## 19V-177

Manufacturer Name: Jayco, Inc.
Submission Date: MAR 06, 2019
NHTSA Recall No.: 19V-177
Manufacturer Recall No.: 9903429



#### **Manufacturer Information:**

Manufacturer Name: Jayco, Inc.

Address: 903 South Main Street

PO Box 460 Middlebury IN 46540

Company phone: 800-283-8267

## **Population:**

Number of potentially involved : 8 Estimated percentage with defect : 100%

#### **Vehicle Information:**

Vehicle 1: 2019-2020 Jayco Class A motor home Embark

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : Power Train : NR

Descriptive Information: 2019 Embark

K1NE0062-0063 NG0054-0056 NJ0065-0066

2020 Embark L1NJ0051

Supplier's date ranage of delivery using roller in hitch to assist unloading chassis -

matched to production records for unit serial numbers

Production Dates: DEC 04, 2018 - FEB 06, 2019

VIN Range 1 : Begin : NR End : NR Not sequential

#### **Description of Defect:**

Description of the Defect: -To assist with delivery, MorRyde(inserted a roller into the hitch. This

fractured the hitch in the upper corners of the receiver opening. Hitch receiver

is compromised

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Failure of hitch when in use could increase risk of crash with personal injury

and/or property damage.

Description of the Cause: Supplier delivery method

Identification of Any Warning NR

that can Occur:

## **Supplier Identification:**

## **Component Manufacturer**

Name: NR

Address: NR

NR

Country: NR

#### **Chronology:**

2-4-19 Production reported that they discovered cracks in the receiver hitch of chassi delivered by MorRyde - Investigation began immedialty. Stop ship was placed on units speed with the same type of chassis. Investigation revealed that MorRyde had inserted a roller into the hitch to assist in delivery off their trailer. wk of 2-4-19 MOrRyde stopped this practice when delivery chassis - and Coordinated with Spartan to procure parts to replace hitch on all chassis still on site.2-28-19 Safety Committe reviewed all details of this incident and agreed a Safety Recall is required.

#### **Description of Remedy:**

Description of Remedy Program : Jayco Dealers with remove and replace hitch at no charge

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition noted above

was Corrected in Production:

#### Recall Schedule:

Description of Recall Schedule: Jayco is prepared to release recall upon receipt of Recall # from NHTSA>

Planned Dealer Notification Date : MAR 25, 2019 - MAR 25, 2019 Planned Owner Notification Date : MAR 25, 2019 - MAR 25, 2019

\* NR - Not Reported