OMB Control No.: 2127-0004

Part 573 Safety Recall Report

19V-793

Manufacturer Name: Conel, LLC dba McElrath Trailers

Submission Date: NOV 05, 2019 **NHTSA Recall No.:** 19V-793

Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Conel, LLC dba McElrath Trailers

Address: 3375 Chesnee Hwy

Chesnee SC 29323

Company phone: 814-2220

Population:

Number of potentially involved : NR Estimated percentage with defect : NR

Vehicle Information:

Vehicle 1: 2014-2019 McElrath TBD

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: The factory discovered the side marker LED lights installed during manufacturing did

not include reflex reflector built into the lens and no other reflex reflectors were

installed on sides and rear of trailers.

Production Dates: AUG 11, 2014 - SEP 12, 2019

Description of Noncompliance:

Description of the The factory discovered the side marker LED lights installed during

Noncompliance: manufacturing did not include reflex reflector built into the lens and no other

reflex reflectors were installed on sides and rear of trailers. Also noticed no

outline of tank with white conspicuity tape.

FMVSS 1: 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2: NR

Description of the Safety Risk: The machine may not be visible from the side or rear at night if the side or

rear marker lights have failed. Machine parked with no lights illuminated

could pose a potential safety concern.

Description of the Cause: NR

Identification of Any Warning NR

that can Occur:

Supplier Identification:

Component Manufacturer

Name: NR

Address: NR

NR

Country: NR

Chronology:

August 29, 2019 research of trailer lighting

October 21, 2019 compiled list of affected machines

November 5, 2019 decision to initiate recall for non-reflex reflector trailer lighting

Description of Remedy:

Description of Remedy Program: A field campaign will be initiated to install separate reflex reflectors red

with an SAE (A) marking will be installed on the sides and rear of each of the affected machines. Added white conspicuity tape on tanks to show outline. Customers and dealers will be reimbursed for the labor of

installing the reflex reflector decals.

How Remedy Component Differs The reflex reflectors with an SAE (A) marking will be present on the side from Recalled Component: and rear of the machine, along with the addition of white conspicuity tape on the rear of the tank. Adding additional red/white conspicuity tape to

sides to mark at least 50% length of the trailer.

Identify How/When Recall Condition The reflex reflectors with an SAE (A) marking will be present on the side was Corrected in Production: and rear of the machine, along with the addition of white conspicuity tape on the rear of the tank. Adding additional red/white conspicuity tape to

sides to mark at least 50% length of the trailer.

Recall Schedule:

Description of Recall Schedule: NR

Planned Dealer Notification Date: NR - NR Planned Owner Notification Date: NR - NR

^{*} NR - Not Reported