

Part 573 Safety Recall Report

20V-323

Manufacturer Name : Braun Ambulances**Submission Date :** JUN 04, 2020**NHTSA Recall No. :** 20V-323**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Braun Ambulances

Address : 1170 Production Drive

VAN WERT OH 45891

Company phone : 4192327020

Population :

Number of potentially involved : 31

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2019-2020 Demers Ambulances MXP170E Type I

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : LiquidSpring LLC has determined that a defect which relates to motor vehicle safety exists in a component of certain LiquidSprings rear suspension systems installed on 2019-20 model year RAM 4500/5500 cab chassis, and only suspension systems installed on the above chassis are included in the safety recall. The affected suspension systems have a serial number range 2007563 – 2013191. The suspension system serial number may be found on the serial number plate located on the driver side front frame hanger of the suspension.

Production Dates : SEP 27, 2019 - MAY 08, 2020

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2019-2020 Demers Ambulances MXP150E Type I

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : LiquidSpring LLC has determined that a defect which relates to motor vehicle safety exists in a component of certain LiquidSpring rear suspension systems installed on 2019-20 model year RAM 4500/5500 cab chassis, and only suspension systems installed on the above chassis are included in the safety recall. The affected suspension systems have a serial number range 2007563 – 2013191. The suspension system serial number may be found on the serial number plate located on the driver side front frame hanger of the suspension

Production Dates : SEP 27, 2019 - MAY 08, 2020

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Description of Defect :

Description of the Defect : The affected system component is the rear brake caliper flexible line. The routing of the rear brake caliper flexible lines during the installation of the suspension kit may be causing brake caliper flexible line wear due to contact with a suspension component(s).

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Continued vehicle use with the rear brake caliper flexible line contacting suspension a component(s) may result in partial or complete loss of rear service brakes which could cause damage to the chassis and/or other vehicles, and possibly result in a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : LiquidSpring LLC

Address : 4899 E 400 South
Lafayette INDIANA 47905

Country : United States

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs
from Recalled Component : NR

Identify How/When Recall Condition
was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported