

# Part 573 Safety Recall Report

## 21V-021

**Manufacturer Name :** Keystone RV Company

**Submission Date :** JAN 21, 2021

**NHTSA Recall No. :** 21V-021

**Manufacturer Recall No. :** 21-399



### Manufacturer Information :

Manufacturer Name : Keystone RV Company

Address : PO Box 2000  
2642 Hackberry Drive Goshen IN  
46527

Company phone : 574-535-2100

### Population :

Number of potentially involved : 207

Estimated percentage with defect : 100 %

### Vehicle Information :

Vehicle 1 : 2020-2021 Dutchmen Voltage 3001, 3351, 3521 3531, 3551, 3571, 3951, 3951, 4271

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Model(s) 3001, 3351, 3521 3531, 3551, 3571, 3951, 3951, 4271

Production Dates : JAN 23, 2020 - NOV 24, 2020

VIN Range 1 : Begin : 4YDF39532LZ990722 End : 4YDF35726LZ990865 ☒ Not sequential

VIN Range 2 : Begin : 4YDF3572XMZ990014 End : 4YDF35228MZ990603 ☒ Not sequential

### Description of Defect :

Description of the Defect : It has been decided that the vehicles in the recall population fail to conform to the requirements of Part 567, "Certification." The vehicles subject to this recall may have been manufactured with the incorrect information on the Federal Identification Tag. The tag indicates the tire pressure as 110 PSI. The correct tire pressure is 95 PSI.

FMVSS 1 : 567 - Certification

FMVSS 2 : NR

Description of the Safety Risk : An incorrect label may lead to unintentionally overinflating the tires, increasing the risk of a crash.

Description of the Cause : The incorrect tire pressure information was printed on the label.

Identification of Any Warning that can Occur : PSI on the Federal Identification Tag does not match information for the rim and tire.

### Involved Components :

Component Name 1 : Fed Tag

Component Description : Label - Tread Gen Fed Cert Combo Laser - 9/05 - FD316

Component Part Number : 192406

### Supplier Identification :

#### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

### Chronology :

01/13/2021 – Report was made by engineering that the FED ID tag info was incorrect for the tire PSI.

01/18/2021 – Range and Scope completed.

### Description of Remedy :

Description of Remedy Program : The remedy is to replace the Federal Identification Tag. Manufacturer Reimbursement Plan on file as of 10/07/2020. General reimbursement plan to be updated every two years. New vehicles are covered under warranty.

How Remedy Component Differs from Recalled Component : The repair will conform to requirements of Part 567, "Certification."

Identify How/When Recall Condition was Corrected in Production : Units were quarantined, inspected then repaired as indicated by inspection.

### Recall Schedule :

Description of Recall Schedule : Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.

Planned Dealer Notification Date : FEB 18, 2021 - FEB 18, 2021

Planned Owner Notification Date : FEB 18, 2021 - FEB 18, 2021

\* NR - Not Reported