OMB Control No.: 2127-0004

Part 573 Safety Recall Report

21V-164

Manufacturer Name: Kia Motors America

Submission Date: MAR 11, 2021 NHTSA Recall No.: 21V-164 Manufacturer Recall No.: SC207



Manufacturer Information:

Manufacturer Name: Kia Motors America

Address: 111 Peters Canyon Road

Irvine CA 92606

Company phone: 800-333-4542

Population:

Number of potentially involved : 142 Estimated percentage with defect : 100 %

Vehicle Information:

Vehicle 1: 2021-2021 Kia Telluride

Vehicle Type: LIGHT VEHICLES

Body Style : ALL Power Train : GAS

Descriptive Information: Certain 2021MY K5 vehicles manufactured from February 3, 2021 through March 4,

2021 (124 vehicles) and certain 2021MY Kia Telluride vehicles manufactured from February 16, 2021 through March 3, 2021 (17 vehicles) at Kia Motors Manufacturing Georgia (KMMG), and certain 2021 Kia Forte vehicles manufactured on February 9,

2021 (1 vehicle) at Kia Motors Mexico (KMM).

The recall population was determined by a review of supplier and vehicle production

records. The vehicles subject to this recall were not produced in VIN order.

Customers seeking information about their specific vehicle will be referred to Kia's

Consumer Assistance Center or their Kia dealer.

Production Dates: FEB 16, 2021 - MAR 03, 2021

VIN Range 1 : Begin : NR End : NR Not sequential

VIN Range 1: Begin:

■ Not sequential

Vehicle 2:	2021-2021 Kia K5
Vehicle Type :	LIGHT VEHICLES
Body Style :	
Power Train :	
Descriptive Information :	Certain 2021MY K5 vehicles manufactured from February 3, 2021 through March 4, 2021 (124 vehicles) and certain 2021MY Kia Telluride vehicles manufactured from February 16, 2021 through March 3, 2021 (17 vehicles) at Kia Motors Manufacturing Georgia (KMMG), and certain 2021 Kia Forte vehicles manufactured on February 9, 2021 (1 vehicle) at Kia Motors Mexico (KMM).
	The recall population was determined by a review of supplier and vehicle production records. The vehicles subject to this recall were not produced in VIN order. Customers seeking information about their specific vehicle will be referred to Kia's Consumer Assistance Center or their Kia dealer.
Production Dates:	FEB 03, 2021 - MAR 04, 2021
VIN Range 1:	
Vehicle 3:	2021-2021 Kia Forte
	LIGHT VEHICLES
Body Style :	
Power Train :	
	Certain 2021MY K5 vehicles manufactured from February 3, 2021 through March 4, 2021 (124 vehicles) and certain 2021MY Kia Telluride vehicles manufactured from February 16, 2021 through March 3, 2021 (17 vehicles) at Kia Motors Manufacturing Georgia (KMMG), and certain 2021 Kia Forte vehicles manufactured on February 9, 2021 (1 vehicle) at Kia Motors Mexico (KMM).
	The recall population was determined by a review of supplier and vehicle production records. The vehicles subject to this recall were not produced in VIN order. Customers seeking information about their specific vehicle will be referred to Kia's Consumer Assistance Center or their Kia dealer.
Production Dates :	FEB 09, 2021 - FEB 09, 2021

End: NR

NR

Description of Noncompliance:

Description of the The subject vehicles are equipped with an Occupant Classification/Detection

Noncompliance : System (OCS/ODS) that detects the presence of a child restraint system in the

front passenger seat. FMVSS 208, Section 19.2.1 requires the vehicle's OCS/ODS to deactivate the airbag system when a child restraint system (CRS) is detected in the front passenger seat. The OCS/ODS unit was improperly calibrated by the OCS/ODS supplier. If the OCS/ODS unit is not calibrated properly, the requirements of FMVSS 208 noted above will not be met thereby

increasing the risk of injury to child in a CRS in a crash.

FMVSS 1: 208 - Occupant crash protection

FMVSS 2: NR

Description of the Safety Risk: Increased risk of injury to a child in a CRS due to deployment of the front

passenger airbag in a crash

Description of the Cause: Improper calibration of ODS/OCS unit.

Identification of Any Warning The "PASSENGER AIRBAG OFF" indicator light remains turned off

that can Occur:

Involved Components:

Component Name 1: Telluride: ODS Unit

Component Description: Occupant Detection System Unit

Component Part Number: 80702-S9000

Component Name 2: K5: OCS Unit

Component Description: Occupant Classification System Unit

Component Part Number: 80702-L2000

Component Name 3: Forte: OCS Unit

Component Description : Occupant Classification System Unit

Component Part Number: 80702-M6000

Supplier Identification:

Component Manufacturer

Name: IEE, S.A.

Address: 1, rue du Campus

L-7795 Bissen Foreign States

Country: Luxembourg

Chronology:

See attached document titled "2021MY K5, Telluride and Forte OCS/ODS Chronology"

Description of Remedy:

Description of Remedy Program: All owners of the subject vehicles will be notified by first class mail with

instructions to bring their vehicles to have the OCS/ODS Unit replaced with a new one. Once installed, the dealer will also initialize/reset the ODS/OCS unit. Kia will reimburse owners for repair expenses already incurred pursuant to Kia's General Reimbursement Plan filed May 11,

2020.

How Remedy Component Differs The remedy component is a properly calibrated OCS/ODS Unit.

from Recalled Component:

Identify How/When Recall Condition The supplier replaced the problematic relay/calibration board with an was Corrected in Production: improved one on February 25, 2021. Components manufactured before February 25, 2021 were installed in K5, Telluride and Forte vehicles produced from February 3 through March 4, 2021 (248 vehicles). Of those vehicles, 142 were sold to dealers and/or customers. The remaining 106 vehicles were repaired prior to delivery to dealers.

Recall Schedule:

Description of Recall Schedule: The Dealer Notification is planned for March 16, 2021 and the Owner

Notification is planned for March 18, 2021.

Planned Dealer Notification Date: MAR 16, 2021 - MAR 16, 2021 Planned Owner Notification Date: MAR 18, 2021 - MAR 18, 2021

* NR - Not Reported