OMB Control No.: 2127-0004

Part 573 Safety Recall Report

21V-571

Manufacturer Name: Newmar Corporation

NHTSA Recall No.: 21V-571

Manufacturer Recall No.: 21E 047



Manufacturer Information:

Manufacturer Name: Newmar Corporation

Address: 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone: 574-773-7791

Population:

Number of potentially involved: 2,169 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2019-2021 Newmar Bay Star

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : Power Train : NR

Descriptive Information: On certain motorhomes, Lippert is recalling Hehr 6400 series window vents built

between 10/01/2018 and 08/13/2020. The adhesive that bonds the vented portion of the window may fail. Adhesive failure may cause the vent portion of the window to

detach, increasing the risk of a crash or injury. Bay Star= 43

Production Dates: OCT 01, 2018 - OCT 21, 2021

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 2: 2019-2020 Newmar Canyon Star Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : Power Train : NR

Descriptive Information: On certain motorhomes, Lippert is recalling Hehr 6400 series window vents built

between 10/01/2018 and 08/13/2020. The adhesive that bonds the vented portion of the window may fail. Adhesive failure may cause the vent portion of the window to

detach, increasing the risk of a crash or injury. Canyon Star=17

Production Dates: OCT 01, 2018 - OCT 21, 2021

Vehicle 3:	2019-2020 New	mar Bay Star S	port			
Vehicle Type :	BUSES, MEDIUM	•	-			
Body Style : Power Train :						
Descriptive Information :	On certain motorhomes, Lippert is recalling Hehr 6400 series window vents built					
	between $10/01/2018$ and $08/13/2020$. The adhesive that bonds the vented portion of the window may fail. Adhesive failure may cause the vent portion of the window to detach, increasing the risk of a crash or injury. Bay Star Sport=12					
Production Dates:	OCT 01, 2018 - OCT 21, 2021					
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential	
	2018-2021 New					
V -	BUSES, MEDIUM	I & HEAVY VEH	ICLES			
Body Style :	ND					
Power Train:						
Descriptive Information :	On certain motorhomes, Lippert is recalling Hehr 6400 series window vents built between $10/01/2018$ and $08/13/2020$. The adhesive that bonds the vented portion of the window may fail. Adhesive failure may cause the vent portion of the window to detach, increasing the risk of a crash or injury. Dutch Star=1,047					
Production Dates:	OCT 01, 2018 - 0	OCT 21, 2021				
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential	
Vehicle 5:	2020-2020 New	mar Kountry S	tar			
Vehicle Type : Body Style :	BUSES, MEDIUM & HEAVY VEHICLES					
Power Train :						
Descriptive Information :	: On certain motorhomes, Lippert is recalling Hehr 6400 series window vents built between 10/01/2018 and 08/13/2020. The adhesive that bonds the vented portion of the window may fail. Adhesive failure may cause the vent portion of the window to detach, increasing the risk of a crash or injury. Kountry Star=47					
Production Dates:	OCT 01, 2018 - 0	OCT 21, 2021				
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential	
	2019-2019 New					
V -	BUSES, MEDIUM	I & HEAVY VEH	ICLES			
Body Style :	1.70					
Power Train :						
Descriptive Information :				o .		
	between 10/01/2018 and 08/13/2020. The adhesive that bonds the vented portion of the window may fail. Adhesive failure may cause the vent portion of the window to					
	detach, increasing the risk of a crash or injury. Ventana LE=38					
Production Dates :		9		U		
VIN Range 1:		NR	End:	NR	☐ Not sequential	

	2019-2021 New BUSES, MEDIUM		ICLES			
Power Train:	NR					
Descriptive Information :	On certain motorhomes, Lippert is recalling Hehr 6400 series window vents built between $10/01/2018$ and $08/13/2020$. The adhesive that bonds the vented portion of the window may fail. Adhesive failure may cause the vent portion of the window to detach, increasing the risk of a crash or injury. Ventana= 502					
Production Dates:	OCT 01, 2018 - C	OCT 21, 2021				
VIN Range 1:	Begin :	NR	End:	NR	■ Not sequential	
Vehicle Type : Body Style : Power Train :						
		O	crash oi	r injury. Essex=42		
Production Dates:						
VIN Range 1:	Begin :	NR	End:	NR	■ Not sequential	
	2019-2020 New BUSES, MEDIUM NR	J	ICLES			
Descriptive Information :	On certain motorhomes, Lippert is recalling Hehr 6400 series window vents built between $10/01/2018$ and $08/13/2020$. The adhesive that bonds the vented portion of the window may fail. Adhesive failure may cause the vent portion of the window to detach, increasing the risk of a crash or injury. King Aire= 60					
Production Dates:	OCT 01, 2018 - 0	OCT 21, 2021				
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential	
	2019-2020 New BUSES, MEDIUM NR					
Descriptive Information : On certain motorhomes, Lippert is recalling Hehr 6400 series window vents built between $10/01/2018$ and $08/13/2020$. The adhesive that bonds the vented portion of the window may fail. Adhesive failure may cause the vent portion of the window to detach, increasing the risk of a crash or injury. London Aire=78						
Production Dates :	OCT 01, 2018 - 0	OCT 21, 2021				
VIN Range 1:	Begin :	NR	End:	NR	☐ Not sequential	

	Vehicle 11: 20	019-2020 Ne	ewmar Mour	ntain Aire				
	Vehicle Type: Bl	Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES						
	Body Style :							
	Power Train: N	R						
	be	On certain motorhomes, Lippert is recalling Hehr 6400 series window vents built between $10/01/2018$ and $08/13/2020$. The adhesive that bonds the vented portion of the window may fail. Adhesive failure may cause the vent portion of the window to detach, increasing the risk of a crash or injury. Mountain Aire= 80						
	Production Dates: 0	CT 01, 2018	- OCT 21, 20	21				
	VIN Range 1: Beg	gin:	NR	End: NR	☐ Not sequential			
	Vehicle 12: 20 Vehicle Type: Bl Body Style: Power Train: N	USES, MEDIU R	J M & HEAVY	VEHICLES	O goving veindov venta hvilt			
	of de	etween 10/0 the window etach, increa	1/2018 and may fail. Ac sing the risk	08/13/2020. The adhesive lhesive failure may cause the of a crash or injury. New A	that bonds the vented portion e vent portion of the window to			
	Production Dates: 00 VIN Range 1: Be		- OC1 21, 20 NR	End: NR	☐ Not sequential			
	VIIV Range 1.Des	5111 .	TVIC	Liid. Wit	Not sequential			
D	Description of Defect :							
	Description of the Defect :		y cause the v	-	window may fail. Adhesive to detach, increasing the risk			
	FMVSS 1:	NR						
	FMVSS 2:	NR						
Ι	Description of the Safety Risk :	built betweented por	een 10/01/2 tion of the v	s, Lippert is recalling Hehr (2018) and 08/13/2020. The vindow may fail. Adhesive for to detach, increasing the ris	adhesive that bonds the ailure may cause the vent			
	Description of the Cause :	The adhesi	ive that bond	ds the vented portion of the	window may fail.			
	Identification of Any Warning that can Occur :							
_								
Tı	nvolved Components :							
	-							
	<u>-</u>							

Component Name 1: NR
Component Description: NR
Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: Lippert Components, Inc.

Address: P.O. Box 2888

Elkhart Indiana 46515

Country: United States

Chronology:

On 7/20/2021 NHTSA reached out by email with Lippert 21E 047, Lippert confirmed recall 21E 047 has been started. Today on 07/27/2021, Newmar is giving notice to NHTSA of a safety defect on Newmar motorhomes.

Description of Remedy:

Description of Remedy Program : Newmar Dealers will inspect the windows, and replace the vent if

necessary, free of charge. Newmar Corporation will be conducting this

recall in its entirety.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: On or before 09/25/2021 customer/dealer letters will be mailed out.

Planned Dealer Notification Date: SEP 25, 2021 - SEP 25, 2021 Planned Owner Notification Date: SEP 25, 2021 - SEP 25, 2021

* NR - Not Reported