

# Part 573 Safety Recall Report

## 22V-161

**Manufacturer Name :** KZRV, L.P.**Submission Date :** MAR 16, 2022**NHTSA Recall No. :** 22V-161**Manufacturer Recall No. :** KZ-2022-01**Manufacturer Information :**

Manufacturer Name : KZRV, L.P.

Address : 0985 N 900W

Shipshewana IN 46565

Company phone : 800-768-4016x154/153

**Population :**

Number of potentially involved : 1,054

Estimated percentage with defect : 25 %

**Vehicle Information :**

Vehicle 1 : 2022-2022 KZ RV Stratus

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : The vehicles subject to this recall may be equipped with a defective coupler.

Production Dates : SEP 14, 2021 - OCT 27, 2021

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 2 : 2022-2022 KZ RV Connect

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : The vehicles subject to this recall may be equipped with a defective coupler.

Production Dates : SEP 14, 2021 - OCT 27, 2021

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 3 : 2022-2022 KZ RV Sonic

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : The vehicles subject to this recall may be equipped with a defective coupler.

Production Dates : SEP 14, 2021 - OCT 27, 2021

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Vehicle 4 : 2022-2022 KZ RV SportTrek

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : The vehicles subject to this recall may be equipped with a defective coupler.

Production Dates : SEP 14, 2021 - OCT 27, 2021

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

### Description of Defect :

Description of the Defect : The frame coupler may have incomplete or missing welds.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The coupler welds could fail and may cause trailer/tow vehicle separation which may lead to an increased risk of a crash and personal injury.

Description of the Cause : Component supplier error.

Identification of Any Warning that can Occur : Broken or incomplete welds visible on bottom of coupler.

### Involved Components :

Component Name 1 : Coupler

Component Description : NR

Component Part Number : NR

### Supplier Identification :

#### Component Manufacturer

Name : Pacific Trailer Products, Inc.

Address : 19120 SE 34th St. Suite 105  
Vancouver Washington 98683

Country : United States

**Chronology :**

3/4/22 - KZ is notified by the frame manufacture of a potential defect.  
3/7/22 - KZ researches the supplier data and internal purchasing records.  
3/9/22 - KZ confirms it may have received frames equipped with the defective couplers from the frame manufacturer Norco.  
3/10/22 - KZ holds safety committee meeting and determines a recall needs to be filed.

**Description of Remedy :**

Description of Remedy Program : Inspection for defect . If defect is confirmed replace coupler. This replacement will be done at no cost to the owner. Reimbursement will be following the general reimbursement plan that is on file with NHTSA.

How Remedy Component Differs from Recalled Component : The remedy coupler is fully welded on the bottom side.

Identify How/When Recall Condition was Corrected in Production : Supplier corrected.

**Recall Schedule :**

Description of Recall Schedule : KZ will notify the dealers and owners of these recreational vehicles by letter. A final copy of the owner letter and dealer repair instructions will be provided to NHTSA.

Planned Dealer Notification Date : MAY 01, 2022 - MAY 01, 2022

Planned Owner Notification Date : MAY 01, 2022 - MAY 01, 2022

\* NR - Not Reported