

Consumer Alert: Do Not Ride Recall Issued for Can-Am Ryker Motorcycles

Bombardier Recreational Products says handlebar stem bolts may break suddenly

July 20, 2022 | Washington, DC

Bombardier Recreational Products is warning owners of certain 2022 Can-Am Ryker motorcycles not to drive them. [Bombardier is recalling](#) more than 9,300 vehicles with a handlebar stem bolt that may break suddenly, which could lead to a loss of steering control and increase the risk of a crash.

Bombardier Recreational Products highly recommends that owners stop riding their vehicle until the recall repair is performed.

Next Steps

1. Owners are encouraged to immediately contact their authorized BRP Can-Am On-Road dealer to schedule an appointment to have the FREE safety recall performed on their vehicle.
2. The dealer will clean the threads of the steering column and install the new handlebar stem bolt.
3. The repair will take less than one hour to complete.

Vehicle owners can visit [NHTSA.gov/recalls](https://www.nhtsa.gov/recalls) and enter their vehicle identification number to see if their vehicle is under recall. NHTSA encourages everyone to download its [SaferCar app](#) to stay informed about current recalls.

Contact:

NHTSA

NHTSA MediaNHTSAmedia@dot.gov[202-366-9550](tel:202-366-9550)