OMB Control No.: 2127-0004

Part 573 Safety Recall Report

22V-856

Manufacturer Name: Shyft Group
Submission Date: NOV 18, 2022
NHTSA Recall No.: 22V-856
Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Shyft Group

Address: 1541 Reynolds Road

Charlotte MI 48813

Company phone: 517-543-6400

Population:

Number of potentially involved : 153 Estimated percentage with defect : 100 %

Vehicle Information:

Vehicle 1: 2023-2023 Utilimaster Walk-In Vans

Vehicle Type : LIGHT VEHICLES

Body Style: UNKNOWN

Power Train: GAS

Descriptive Information: The basis of this recall is related to a change in suppliers where the supplier built to

the part to print as opposed to an undocumented change request.

Production Dates: AUG 01, 2022 - OCT 10, 2022

Description of Defect:

Description of the Defect: The retaining nut that holds the shock mount together may not have proper

thread engagement and may be missing a tacked weld to hold the retaining nut in place. The retaining nut could come loose resulting in the bumper separating

from the vehicle.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: A bumper separating from the vehicle could result in the bumper becoming

unexpected road debris which could increase the risk of a crash.

Description of the Cause: Pending

Identification of Any Warning Retaining nuts might separate without warning. A

that can Occur:

Involved Components:

Component Name 1: NR
Component Description: NR
Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: NR Address: NR NR

Country: NR

Chronology:

NR

Description of Remedy:

Description of Remedy Program: NR
How Remedy Component Differs NR
from Recalled Component:

Identify How/When Recall Condition NR
was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: NR

Planned Dealer Notification Date : NR - NR Planned Owner Notification Date : NR - NR

^{*} NR - Not Reported