

# Part 573 Safety Recall Report

## 23V-186

**Manufacturer Name :** KENTUCKY TRAILER MANUFACTURING**Submission Date :** MAR 20, 2023**NHTSA Recall No. :** 23V-186**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :**

**Manufacturer Name :** KENTUCKY TRAILER  
MANUFACTURING  
**Address :** 7201 LOGISTICS DRIVE  
LOUISVILLE KY 40258  
**Company phone :** 502-637-2551

**Number of potentially involved :** 5  
**Estimated percentage with defect :** 1 %

**Vehicle Information :**

**Vehicle 1 :** 2021-2022 Kentucky Trailer (KTSV) XL-12  
**Vehicle Type :** TRAILERS  
**Body Style :**  
**Power Train :** NR

**Descriptive Information :** The recall population was determined by researching the specific trailers that Kentucky Trailer manufactured and sold equipped with the WARN winches that are the subject of Recall 22E-101. The recalled products differ from products that were not included in the recall in that the recalled products were equipped with WARN winches that are the subject of Recall 22E-101 and the non-recalled products were not equipped with WARN winches that are the subject of Recall 22E-101. There are a total of five (5) affected products related to this make/model/model year combination.

**Production Dates :** JUN 30, 2021 - AUG 10, 2022**VIN Range 1 : Begin :** 1KKVF5321ML248718 **End :** 1KKVF5329NL252081 ☐ Not sequential**Description of Defect :**

**Description of the Defect :** After investigating field reports of inadvertent activation, Warn Industries, Inc. determined that, in certain modes of its winches, getting the remote control wet could result in water ingress and corrosion inside the remote control. This condition could lead to inadvertent activation. It was determined that this condition only affects remote controls with wireless capability that are not water proof.

**FMVSS 1 :** NR**FMVSS 2 :** NR

**Description of the Safety Risk :** This condition could cause the winch to start operating when not intended, or to not turn off when switch button is released, resulting in injury to person or

Description of the Cause : property.  
Getting the remote control wet, resulting in water ingress and corrosion inside the remote control.

Identification of Any Warning that can Occur : The vehicle driver or winch operator may hear the winch motor running when not intended.

### Involved Components :

Component Name 1 : VR EVO 8 Winch

Component Description : Warn (brand) Winch

Component Part Number : 103250

### Supplier Identification :

#### Component Manufacturer

Name : Warn Industries, Inc.

Address : 12900 SE Capps Rd.  
Clackamas Oregon 97015

Country : United States

### Chronology :

NR

### Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

### Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported