OMB Control No.: 2127-0004

Part 573 Safety Recall Report

23V-495

Manufacturer Name: Titan Bus
Submission Date: JUL 18, 2023
NHTSA Recall No.: 23V-495
Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Titan Bus

Address: 804 N. Pratt St.

Ottawa OH 45875

Company phone: 4195233593

Population:

Number of potentially involved : 69 Estimated percentage with defect : 100 %

Vehicle Information:

Vehicle 1: 2017-2021 Chevrolet CG33503, CG33803,

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER Power Train : GAS

Descriptive Information: 49 CFR 573.6 Defect and Noncompliance Information Report - NHTSA No. C20200900

Buses Missing Label

69 affected Buses

Production Dates: DEC 15, 2017 - MAR 16, 2021

VIN Range 1: Begin: 1GB3GRBG3H1232190 End: 1HA6GUB71MN000178 ✓ Not sequential

Description of Noncompliance:

Description of the Titan SRW and DRW school and multi-function school activity bus did not meet

Noncompliance: the requirements of S9.3c for the Cross View Mirror Warning Label. When the

average radius of curvature of a mirror is less than 889 mm, the bus must come equipped with a cross view mirror label. The average radius of curvature for the rearview mirrors were less than 889mm, but the bus did not come

equipped with a cross view mirror label.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: The driver is not warned by a label and could use the Cross View Mirrors

while moving. Images in such mirrors do not accurately show another

vehicle's location. The mirror's intended use is for viewing pedestrians while

the bus is stopped.

Description of the Cause: Warning label was not installed during manufacturing of the bus.

Identification of Any Warning NR that can Occur:

Involved Components:

Component Name 1: Cross View Warning Label

Component Description: 1 1/2" x 2 1/2" label

Component Part Number: Generic label

Supplier Identification:

Component Manufacturer

Name: NR

Address: NR

NR

Country: NR

Chronology:

Started production of buses and was notified by the National Highway and Transportation Safety Administration. (Crash Unit). The label for the Cross View Mirror was missing. 49 CFR 573.6 - Defect and Noncompliance Notification.

Description of Remedy:

Description of Remedy Program: Missing warning label.

Titan Bus, LLC has a label included with the notice that we recommend installing on the vehicles to ensure the safety issue is resolved and that the vehicle is safe to operate. Titan Bus LLC also instructed the owners of the location to install the label along with pictures to identify the location.

How Remedy Component Differs The label was missing and is now included in the notification letter.

from Recalled Component:

Identify How/When Recall Condition The warning label is now installed in the vehicles during production.

was Corrected in Production :

Recall Schedule:

Description of Recall Schedule : The recall notifications and labels went out on 5/11/2023 to 6/15/2023.

Titan Bus LLC submitted a TSB to the MC portal instead of this location. We were notified and are now filling out the 573 Report. I could not back

date the start and end date.

Planned Dealer Notification Date : JUL 18, 2023 - JUL 18, 2023 Planned Owner Notification Date : JUL 18, 2023 - JUL 18, 2023

* NR - Not Reported