

Part 573 Safety Recall Report

24V-171

Manufacturer Name : Winnebago Industries, Inc.

Submission Date : MAR 01, 2024

NHTSA Recall No. : 24V-171

Manufacturer Recall No. : 182



Manufacturer Information :

Manufacturer Name : Winnebago Industries, Inc.

Address : PO BOX 152
605 W. Crystal Lake Rd. Forest City IA
50436

Company phone : 1-641-585-3535

Population :

Number of potentially involved : 136

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2024-2024 Winnebago Solis

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined by identifying all Solis 36B floorplans produced.

Production Dates : JUN 30, 2023 - FEB 24, 2024

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : Affected units were built with a standard outlet in the lavatory area that should have been GFCI protected.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Under certain conditions, lack of proper circuit protection can result in electrical shock.

Description of the Cause : The product was designed with an incorrect outlet.

Identification of Any Warning NR
that can Occur :

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

On or about January 26, 2024, Winnebago Design Engineering identified an incorrect outlet placed in the bath area. An investigation was initiated to determine scope of the affected product. The Product Safety Committee met on February 23, 2024 and decided to issue a voluntary recall.

Winnebago is not aware of any injuries as a result of the recall condition.

Description of Remedy :

Description of Remedy Program : Reimbursement request will fall under the general reimbursement plan on file with NHTSA

How Remedy Component Differs from Recalled Component : The remedy component will be a replacement outlet that provided GFCI protection.

Identify How/When Recall Condition was Corrected in Production : The recall condition was corrected in production by changing the previous outlet to one that offers GFCI protection.

Recall Schedule :

Description of Recall Schedule : The recall schedule will be within the 60 day requirement.

Planned Dealer Notification Date : MAR 08, 2024 - MAR 08, 2024

Planned Owner Notification Date : APR 26, 2024 - APR 26, 2024

* NR - Not Reported