8

Part 573 Safety Recall Report

Manufacturer Name :Airstream, Inc.Submission Date :MAY 03, 2024NHTSA Recall No. :24V-314Manufacturer Recall No. :NR

Manufacturer Information :

Manufacturer Name : Airstream, Inc.

Address : 419 West Pike Street PO Box 629 Jackson Center OH 45334-0629 Company phone : 937-596-6111

Vehicle Information :

Vehicle 1:	2023-2024 Airstream Atlas	
Vehicle Type :	BUSES, MEDIUM & HEAVY VEHICLES	
Body Style :	VAN	
Power Train :	DIESEL	
Descriptive Information :	The recall population was established by reviewing the installation process and determined the deficiency began occurring due to a change in Production personnel.	
Production Dates :	AUG 14, 2023 - MAR 26, 2024	
VIN Range 1:	Begin: 1B9KUWH25RJ307992 End: 1B9KUWH29RJ311477 Dot sequential	

Description of Defect :

Description of the Defect :	Units that do not have the heat shield installed; the subflooring material would be exposed to the heat produced by the generator.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	If the flooring was exposed to the heat produced by the generator for an extended amount of time, it increases the potential for fire which could result in personal injury.
Description of the Cause :	Due to employee turnover, we are attributing the root cause to deficiencies in internal training for new employees.
Identification of Any Warning that can Occur :	The owner could potentially smell something burning.

Involved Components :

The information contained in this report was submitted pursuant to 49 CFR §573



Number of potentially involved :

Estimated percentage with defect : 100 %

Population :

$\mathbf{24V}\textbf{-}\mathbf{314}$

Part 573 Safety Recall Report

Component Name 1: GENERATOR HEAT SHIELD

Component Description : 33.00" x 18.00" Galvanized Steel

Component Part Number: 455216

Supplier Identification :

Component Manufacturer

Name : NR Address : NR NR Country : NR

Chronology :

4/22/2024 - Airstream identifies the error in the generator heat shield installation process.

4/22/2024 - Airstream begins investigation.

4/26/2024 - The safety committee reviews all known data and determines a recall is warranted. Airstream is unaware of any warranty or injury claims due to this non-compliance.

Description of Remedy :

Description of Remedy Program :	Airstream will provide it's dealers with the parts and procedure to remedy these units affected by the recall. This will be done at no cost to the owner. Reimbursement will follow the general reimbursement policy that is on file with NHTSA.
How Remedy Component Differs from Recalled Component :	The heatshield will be in place, mounted above the generator.
Identify How/When Recall Condition was Corrected in Production :	The issue was corrected in production on April 22, 2024.

Recall Schedule :

Description of Recall Schedule :	Airstream has the utmost urgency in notifying owners about a recall that affects their vehicle. Letters will be sent out once all pertinent
	information has been gathered.
Planned Dealer Notification Date :	JUL 02, 2024 - JUL 02, 2024
Planned Owner Notification Date :	JUL 02, 2024 ⁻ JUL 02, 2024

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

24V-314

Page 3

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573