#### OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

## 24V-323

Manufacturer Name: Spartan Fire, LLC
Submission Date: MAY 10, 2024
NHTSA Recall No.: 24V-323



#### **Manufacturer Information:**

Manufacturer Name: Spartan Fire, LLC

Manufacturer Recall No.: 24007

Address: 1541 Reynolds Road

Charlotte MI 48813

Company phone: 517-588-4700

## **Population:**

Number of potentially involved: 44 % Estimated percentage with defect: 4 %

#### **Vehicle Information:**

Vehicle 1: 2022-2024 Spartan Fire Gladiator, Metro Star, and FC-94

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER Power Train : DIESEL

Descriptive Information: The basis for this recall population is vehicles equipped with a Valor seat installed

within the production dates listed.

Quantity 1 – Metro Star 2022 model year truck affected. Quantity 3 – Gladiator 2022 model year trucks affected. Quantity 4 – Metro Star 2023 model year trucks affected. Quantity 2 – Gladiator 2023 model year trucks affected. Quantity 1 – FC-94 2023 model year truck affected.

Quantity 13 – Metro Star 2024 model year trucks affected. Quantity 1 – Gladiator 2024 model year truck affected. Quantity 19 – FC-94 2024 model year trucks affected.

Production Dates: JAN 24, 2023 - MAR 07, 2024

VIN Range 1: Begin: NR End: NR

#### Not sequential

## **Description of Noncompliance:**

Description of the An undersized fastener installed during seat installation could potentially

Noncompliance : cause the seat mounting to fail during a loaded condition. As such, these

vehicles may fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 207, "Seating Systems". (FMVSS 571.49 CFR

Part 207 S5)

FMVSS 1: 207 - Seating systems

FMVSS 2: NR

Description of the Safety Risk: If this condition exists, the seat fastener may fracture or pull out of the mount,

resulting in inadvertent seat movement and possible injury.

Description of the Cause: Still investigating root cause.

**Identification of Any Warning None** 

that can Occur:

### **Involved Components:**

Component Name 1: Valor Seat

Component Description : Seats

Component Part Number: NR

#### **Supplier Identification:**

## **Component Manufacturer**

Name: NR Address: NR

NR

Country: NR

#### **Chronology:**

April 2, 2024 – Spartan production found chassis cab with incorrect fasteners installed on seat during inspection. Quality alert issued to production.

April 4 – April 28, 2024 – Spartan investigated the issue, created a PSR team, pulled a potential population, issued quality alert, and request for FEA issued.

April 29, 2024 – Spartan determined the final population.

April 30, 2024 – Conducted a risk assessment. Stop ship issued.

May 1, 2024 - There have been no failures but out of an abundance of caution have decided to escalate the issue for the undersized fasteners. Escalated the issue to REV Group Management.

May 8, 2024 – REV's senior leadership approved a voluntary recall for this issue.

## **Description of Remedy:**

Description of Remedy Program: The affected vehicles will have the seat mount fastener installation

inspected, and corrected when necessary. This will be covered under

normal warranty process.

How Remedy Component Differs The remedy would consist of installing the design intended fasteners.

from Recalled Component:

Identify How/When Recall Condition A quality alert was implemented into production on April 2, 2024. Stop

was Corrected in Production: ship issued on April 30, 2024 across Spartan campuses.

#### **Recall Schedule:**

Description of Recall Schedule: Spartan to begin dealer notifications by the week of May 20, 2024 and

owner notifications by the week of June 17, 2024.

Planned Dealer Notification Date: MAY 24, 2024 - JUN 14, 2024 Planned Owner Notification Date: JUN 17, 2024 - JUN 24, 2024

<sup>\*</sup> NR - Not Reported