OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

# 24V-577

Manufacturer Name: Jayco, Inc.
Submission Date: AUG 01, 2024
NHTSA Recall No.: 24V-577
Manufacturer Recall No.: 9903611



#### **Manufacturer Information:**

Manufacturer Name: Jayco, Inc.

Address: 903 South Main Street

PO Box 460 Middlebury IN 46540

Company phone: 800-283-8267

# **Population:**

Number of potentially involved : 125 Estimated percentage with defect : 100 %

#### **Vehicle Information:**

Vehicle 1: 2024-2025 Entegra Coach Anthem, Aspire, Cornerstone, Reatta, Reatta XL

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER Power Train : DIESEL

Descriptive Information: Jayco Inc. has determined the population from our production records.

Production Dates: OCT 31, 2023 - MAY 28, 2024

VIN Range 1: Begin: 1JSMEACV2R13W8058 End: 1JSMEABU7S1NJ8051 ✓ Not sequential

#### **Description of Defect:**

Description of the Defect: Certain units may have been built in production with the incorrect sized

battery cables, incorrect placement of the battery cables, and improperly torqued battery cables, which are isolated to the coach battery box that

contains a quantity of 2 or 4 - 6 Volt AGM battery option.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Incorrect sized battery cables, incorrect placement of the battery cables, and

improperly torqued battery cables could cause an electrical short and/or

overheat the battery cables, which could increase the risk of a fire.

Description of the Cause: Incorrect Battery Cable Installation in Jayco Inc. Manufacturing.

Identification of Any Warning There is no warning.

that can Occur:

#### **Involved Components:**

Component Name 1: Battery 6V AGM D Cycle

Component Description: BATTERY, 6V AGM D CYCLE L-16 SER AUTO POST W/THD

Component Part Number: 0305307 / REV-L16-400

## **Supplier Identification:**

## **Component Manufacturer**

Name: NR

Address: NR

NR

Country: NR

#### **Chronology:**

6/14/2024 Jayco production notified Jayco Compliance by email regarding certain Entegra Coach models that may have been built in production with the incorrect sized battery cables, incorrect placement of the battery cables, and improperly torqued battery cables, which are isolated to the coach battery box.

6/17/2024 The Warranty Incident Review Committee (WIRC) discussed the incident and elevated it to CPAC. 7/3/2024 The Corrective Preventive Action Committee (CPAC) discussed the incident and elevated it to SSC. 7/25/2024 The Safety Steering Committee (SSC) met and voted to proceed with filing a safety recall with

Jayco is not aware of any warranty claims or any accidents or injuries related to this matter.

# **Description of Remedy:**

Description of Remedy Program: Jayco Inc. dealers will inspect for the incorrect sized battery cables,

incorrect placement of the battery cables, and inspect for improperly torqued battery cables and repair or replace battery cables as necessary. Repairs made prior to the recall will be reimbursed in accordance with our

Recall Reimbursement Plan on file with NHTSA. This repair will be performed at no charge. Jayco Inc. will file completion reports.

How Remedy Component Differs The recalled component will have properly sized battery cables, the from Recalled Component: correct placement of the battery cables, and properly torqued battery

cables.

Identify How/When Recall Condition June 20, 2024, Units in production with the incorrect sized battery cables, was Corrected in Production: incorrect routing of the battery cables, and improperly torqued battery cables, which are isolated to the coach battery box have been remedied. All units built on and after June 20, 2024 will have the properly sized battery cables, the correct placement of the battery cables, and properly torqued battery cables.

#### **Recall Schedule:**

Description of Recall Schedule: Jayco Inc. will notify its dealers and affected retail owners.

Planned Dealer Notification Date: AUG 30, 2024 - AUG 30, 2024 Planned Owner Notification Date: AUG 30, 2024 - AUG 30, 2024

\* NR - Not Reported