

Part 573 Safety Recall Report

24V-766

Manufacturer Name : McNeilus Truck & Manufacturing, Inc.

Submission Date : OCT 15, 2024

NHTSA Recall No. : 24V-766

Manufacturer Recall No. : NR



Manufacturer Information :

Population :

Manufacturer Name : McNeilus Truck & Manufacturing, Inc.

Address : 524 County Road 34 East

P.O. Box 70 Dodge Center MN 55927

Company phone : 5075139310

Number of potentially involved : 431

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2010-2024 McNeilus Rear Loader

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : ALL

Power Train : DIESEL

Descriptive Information : McNeilus Rear Loader refuse trucks built with an option requiring relocation of the license plate. Vehicles outside the recall population have the license plate installed in the standard location.

Production Dates : JUN 25, 2011 - SEP 05, 2024

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Description of Noncompliance :

Description of the Noncompliance : The license plate is illuminated from the bottom of the plate and does not comply with the requirement for license plate illumination location in FMVSS 108.

FMVSS 1 : 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2 : NR

Description of the Safety Risk : A license plate that is not illuminated from the top or sides as required may not provide adequate illumination and may prevent the vehicle from being sufficiently identified in the event of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : None.

Involved Components :

Component Name 1 : License Plate lamp

Component Description : License Plate Lamp

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : McNeilus

Address : 524 East Highway st
Dodge Center Minnesota 55927

Country : United States

Chronology :

August 2024 McNeilus was alerted by a customer that it had received a traffic citation from the police department related to the vehicle's license plate lamp. McNeilus investigated the concern with this particular vehicle and discovered that the lamp on this vehicle was installed at the bottom of the plate, rather than on the top or sides of the license plate. Further investigation was performed in September 2024 to understand whether the issue the customer reported was unique to that truck or a potentially broader issue.. McNeilus' investigation determined that the placement of the license plate lamp at the bottom of the lisence plate related to vehicle option content and that other trucks produced with the option would have similarly had the license plate lamp installed in the same location.

October 15, 2024 McNeilus determined a non-compliance existed and decided to conduct a recall to address affected units in the field. Other than the one citation reported above, McNeilus is not aware of any incidents related to this issue.

Description of Remedy :

Description of Remedy Program : McNeilus will direct customers to have the license plate lamp relocated to meet FMSS 108 requirements. Repairs will be performed by the McNeilus dealer network at no cost to customers.

How Remedy Component Differs from Recalled Component : Plate lamp will illuminate license plate from the top.

Identify How/When Recall Condition was Corrected in Production : A stop ship was performed on any vehicles in McNeilus' s possession that would have had this option.

Recall Schedule :

Description of Recall Schedule :	NR
Planned Dealer Notification Date :	DEC 13, 2024 - DEC 13, 2024
Planned Owner Notification Date :	DEC 13, 2024 - DEC 13, 2024

* NR - Not Reported