Part 573 Safety Recall Report

Manufacturer Name : General Motors, LLC Submission Date : NOV 14, 2024 NHTSA Recall No.: 24V-858 Manufacturer Recall No.: N242481860

Manufacturer Information :

Manufacturer Name : General Motors, LLC

Address: 29427 Louis Chevrolet Road MAIL CODE 480-210-2V WARREN MI 48093 Company phone : 586-596-1733

Vehicle Information :

Vehicle 1:	2024-2024 Chevrolet Expre	ess Cutaway	
Vehicle Type :			
Body Style :			
Power Train :	NR		
Descriptive Information :	Manufacturing records wer	e used to determine the aff	ected vehicles.
	This recall only involves commercial cutaway vehicles with a gross vehicle weight rating (GVWR) under 4536 Kg (10,000 lbs) sold with inside rearview mirror video display (RPO DRJ). Chevrolet Express Passenger and Cargo Vans and vehicles with a GVWR over 4536 Kg (10,000 lbs.) are not included in this recall. Vehicles produced outside of the suspect manufacturing window are not included in this recall. There are 326 Chevrolet Express vehicles affected by this recall.		
Production Dates :	AUG 01, 2024 - SEP 17, 202	4	
VIN Range 1:	Begin : NR	End: NR	□ Not sequential

Population :

Number of potentially involved : 582 Estimated percentage with defect : 1%

云 🔨 🔂

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

24V-858

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Page 2

Vahiala 2		CMC Savana C	utowow	
Vehicle Z Vehicle Type		I GMC Savana C	utaway	
Body Style				
Power Train				
Descriptive Information	: Manufactu	ring records w	ere used to determine the af	fected vehicles.
	rating (GV) video displ 4536 Kg (1 suspect ma	WR) under 453 ay (RPO DRJ). 0,000 lbs.) are mufacturing wi	6 Kg (10,000 lbs.) sold with GMC Savana Passenger and not included in this recall. V indow are not included in thi	Cargo Vans and vehicles over /ehicles produced outside of the is recall.
	There are 2	256 GMC Savan	a vehicles affected by this re	call.
Production Dates	: AUG 01, 20)24 - SEP 17, 20	024	
VIN Range 1	: Begin :	NR	End: NR	□ Not sequential
Description of	the General nce: and GM Motor V vehicles	IC Savana vehic Vehicle Safety S s may be missii		n to Section S6.2 of Federal
Noncomplian FMVS FMVS Description of the Safety R Description of the Cau	IteleviseGeneral Motor V vehicles the wroS 1 :111 - RoS 2 :NRisk :If the re during a rearvier video d	IC Savana vehic Vehicle Safety S s may be missin ong inside rearv ear visibility ear vision came a backing even ar, the manufac w mirror instea isplay.	eles potentially fail to conform tandard (FMVSS) No. 111, "I ng the required rear vision ca view mirror was installed. era display is missing, there is t. turer of these vehicles, instal ad of the mirror with the bui	m to Section S6.2 of Federal Rear Visibility." These amera video display because s increased risk of a crash lled a base-level inside lt-in rear vision camera
Description of Noncomplian FMVS FMVS Description of the Safety R Description of the Cau Identification of Any Warn	ItheGeneral Motor V vehicles the wroS 1 :111 - ReS 2 :NRisk :If the re during a rearview video da	IC Savana vehic Vehicle Safety S s may be missin ong inside rearv ear visibility ear vision came a backing even ar, the manufac w mirror instea isplay. rs, dealers, or o	eles potentially fail to conform tandard (FMVSS) No. 111, "I ng the required rear vision ca view mirror was installed. The display is missing, there is t. turer of these vehicles, instal ad of the mirror with the bui wners may notice that the m	m to Section S6.2 of Federal Rear Visibility." These amera video display because s increased risk of a crash lled a base-level inside lt-in rear vision camera
Description of Noncomplian FMVS FMVS Description of the Safety R Description of the Cau Identification of Any Warn	ItheGeneral Motor V vehicles the wroS 1 :111 - ReS 2 :NRisk :If the re during a rearview video da	IC Savana vehic Vehicle Safety S s may be missin ong inside rearv ear visibility ear vision came a backing even ar, the manufac w mirror instea isplay. rs, dealers, or o	eles potentially fail to conform tandard (FMVSS) No. 111, "I ng the required rear vision ca view mirror was installed. The display is missing, there is t. turer of these vehicles, instal ad of the mirror with the bui wners may notice that the m	m to Section S6.2 of Federal Rear Visibility." These amera video display because s increased risk of a crash lled a base-level inside lt-in rear vision camera
Description of Noncomplian FMVS FMVS Description of the Safety R Description of the Cau Identification of Any Warn that can Occ	ithe General ince : and GM Motor V vehicles the wro the wro S 1 : 111 - Ro S 2 : NR isk : If the reduring a use : Navista rearview video d ning Upfitter cur : connect	IC Savana vehic Vehicle Safety S s may be missin ong inside rearv ear visibility ear vision came a backing even r, the manufact w mirror instea isplay. rs, dealers, or o tion for the har	eles potentially fail to conforn standard (FMVSS) No. 111, "I ng the required rear vision ca view mirror was installed. era display is missing, there is t. turer of these vehicles, instal ad of the mirror with the bui wners may notice that the m ness exiting the headliner in	m to Section S6.2 of Federal Rear Visibility." These amera video display because s increased risk of a crash lled a base-level inside lt-in rear vision camera
Description of Noncomplian FMVS FMVS Description of the Safety R Description of the Cau Identification of Any Warn that can Occ	ite General ince : and GM Motor V vehicles the wro the wro S 1 : 111 - R S 2 : NR isk : If the reduring a use : Navista rearview video d ning Upfitter cur : connect 1 : MIRROR A	IC Savana vehic Vehicle Safety S s may be missin ong inside rearve ear visibility ear vision came a backing even ar, the manufact w mirror insteat isplay. rs, dealers, or o tion for the har	eles potentially fail to conforn itandard (FMVSS) No. 111, "I ng the required rear vision ca view mirror was installed. era display is missing, there is t. turer of these vehicles, instal ad of the mirror with the bui wners may notice that the m ness exiting the headliner in	m to Section S6.2 of Federal Rear Visibility." These amera video display because s increased risk of a crash lled a base-level inside lt-in rear vision camera
Description of Noncomplian FMVS FMVS Description of the Safety R Description of the Safety R Description of the Cau Identification of Any Warn that can Occ	TheGeneral Motor V vehicles the wroS 1 :111 - RoS 2 :NRisk :If the re during a rearvier video d hingIse :Navista rearvier video d hing1 :MIRROR A Base-Leve	IC Savana vehic Vehicle Safety S s may be missin ong inside rearve ear visibility ear vision came a backing even ar, the manufac w mirror insteat isplay. rs, dealers, or o tion for the har ASM-I/S RR VII el Inside Rearv	eles potentially fail to conforn itandard (FMVSS) No. 111, "I ng the required rear vision ca view mirror was installed. era display is missing, there is t. turer of these vehicles, instal ad of the mirror with the bui wners may notice that the m ness exiting the headliner in	m to Section S6.2 of Federal Rear Visibility." These amera video display because s increased risk of a crash lled a base-level inside lt-in rear vision camera

Supplier Identification :

Component Manufacturer

Name : NR Address : NR NR Country : NR

Chronology:

On October 7, 2024, a GM quality engineer submitted this issue to GM's Speak Up For Safety (SUFS) program after regular warranty claim monitoring identified an increase in claims involving inside rearview mirrors on 2024 Express and Savana cutaway products. GM opened a product investigation on October 11, 2024. GM's investigation discovered that Navistar incorrectly installed a base-level inside rearview mirror on some vehicles instead of the mirror with the built-in rear vision camera video display. An analysis of field data completed on October 30, 2024, found 75 complaints potentially related to this condition. These were received by GM between August 19, 2024 and October 7, 2024 and all were traced back to the same Navistar operator. GM is not aware of any accidents or injuries related to this condition. On November 7, 2024, GM's Safety Field Action Decision Authority (SFADA) decided to conduct a noncompliance recall on vehicles with a GVWR under 10,000 lbs. (4536 Kg) assembled by this operator at Navistar's plant from August 1, 2024 to September 17, 2024.

Description of Remedy :

Description of Re	medy Program :	Dealers will inspect and replace the inside rearview mirror, if necessary. Pursuant to 49 C.F.R. § 573.13(d)(1), all covered vehicles are under warranty, so reimbursement is not offered.
5	mponent Differs led Component :	The replacement mirror has a built-in rear vision camera video display.
		Containment efforts were initiated on October 9, 2024, including a yard- hold and implementation of 100% inspection.

Recall Schedule :

Description of Recall Schedule :	Dealers will be notified on November 14, 2024. Customer notification is
	estimated to begin on December 30, 2024
Planned Dealer Notification Date :	NOV 14, 2024 - NOV 14, 2024
Planned Owner Notification Date :	DEC 30, 2024 ⁻ DEC 30, 2024

* NR - Not Reported