

# Part 573 Safety Recall Report

## 24V-887

**Manufacturer Name :** Mitsubishi Fuso Truck of America, Inc.**Submission Date :** NOV 25, 2024**NHTSA Recall No. :** 24V-887**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :**

Manufacturer Name : Mitsubishi Fuso Truck of America, Inc.

Number of potentially involved : 224

Address : 2015 Center Square Road  
Logan Township NJ 08085

Estimated percentage with defect : 100 %

Company phone : 4674500

**Vehicle Information :**

Vehicle 1 : 2016-2020 Mitsubishi Fuso FEC52, FEC72, FEC92

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style : 2-DOOR

Power Train : DIESEL

Descriptive Information : A specific batch of rear spring leaves were determined to be defective. There are 224 trucks produced for this market that were built with springs from that batch.

Production Dates : JAN 01, 2015 - NOV 12, 2019

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential**Description of Defect :**

Description of the Defect : The spring leaf was manufactured with metal of insufficient strength that may break under normal use and maintenance.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the spring leaf breaks, it can fall into the roadway and cause a crash without warning.

Description of the Cause : The cause of the failure is that the spring leaf was manufactured with metal of insufficient strength.

Identification of Any Warning N/A  
that can Occur :**Involved Components :**

Component Name 1 : Rear leaf spring assembly

Component Description : Assembly of spring leaves

Component Part Number : TBD

### Supplier Identification :

#### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

### Chronology :

TBD

### Description of Remedy :

Description of Remedy Program : Replaced the leaf spring assembly at no charge to the customer/dealer. The dealer will be reimbursed through normal recall channels.

How Remedy Component Differs from Recalled Component : TBD

Identify How/When Recall Condition was Corrected in Production : The condition was limited to a specific batch of spring leaves. The next batch produced was manufactured with metal of sufficient strength.

### Recall Schedule :

Description of Recall Schedule : TBD

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported