OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

# 24V-969

**Manufacturer Name:** Nissan North America, Inc.

NHTSA Recall No.: 24V-969
Manufacturer Recall No.: PMA42



#### **Manufacturer Information:**

Manufacturer Name: Nissan North America, Inc.

Address: P. O. BOX 685001

Franklin TN 37068-5009

Company phone: 800-647-7261

# **Population:**

Number of potentially involved : 20 Estimated percentage with defect : 100 %

#### **Vehicle Information:**

Vehicle 1: 2025-2025 Nissan Kicks

Vehicle Type: LIGHT VEHICLES Body Style: HATCHBACK

Power Train: GAS

Descriptive Information: Based on Nissan production records, the issue is specific to Nissan Kicks vehicles that

were part of an in-plant repair activity and produced during the specified vehicle

production period. No other Nissan or INFINITI vehicles are affected.

Production Dates: JUN 24, 2024 - NOV 29, 2024

## **Description of Noncompliance:**

Description of the Noncompliance: On the affected Kicks vehicles, the "Shift-to-Park" warnings may not be activated when the driver turns the vehicle's ignition OFF while the gear selector is in a position other than "Park" and opens the driver side door.

FMVSS 1: 114 - Theft protection

FMVSS 2: NR

Description of the Safety Risk: This condition may not meet the requirements of section S5.1.3. of Federal

Motor Vehicle Standard (FMVSS) No. 114; "Theft Protection and Rollaway Prevention." If the vehicle is not in Park when the ignition is OFF, the vehicle could potentially move unexpectedly, which may increase the risk of accident

or injury.

Description of the Cause: NR

Identification of Any Warning There is no preceding warning.

that can Occur:

### **Involved Components:**

Component Name 1: Body Control Module

Component Description: Body Control Module

Component Part Number: 284B1 7LG0B

# **Supplier Identification:**

# **Component Manufacturer**

Name: Nissan

Address: NR

NR

Country: NR

# **Chronology:**

Chronology will be supplemented.

### **Description of Remedy:**

Description of Remedy Program: Dealers will be instructed to re-configure the vehicle's Body Control Module (BCM) to activate the "Shift-to-Park" warning. All inspections and repairs will be performed free of charge for parts and labor and may take

up to half (0.5) hour to complete.

Nissan will not include a statement in the Part 577 owner notification concerning reimbursement for the cost of obtaining a pre-notification

remedy as the subject vehicles are under warranty.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

#### **Recall Schedule:**

Description of Recall Schedule: Dealers were notified on December 20, 2024. Owners of all potentially

affected vehicles will be notified beginning January 29, 2025.

# **Part 573 Safety Recall Report**

**24V-969** 

Page 3

Planned Dealer Notification Date : DEC 23, 2024 - NR Planned Owner Notification Date : JAN 29, 2025 - NR

\* NR - Not Reported