



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

## Part 573 Safety Recall Report

## 25V331

**Manufacturer Name:** Hyundai Translead

**Submission Date:** May 21, 2025

**NHTSA Recall No.:** 25V331

**Manufacturer Recall No.:** 25E-025

### Manufacturer Information

### Population

**Manufacturer Name:** Hyundai Translead

**Address:** 8880 Rio San Diego Drive,  
#500  
San Diego CA, 92108-164

**Total number of potentially involved:** 2

**Estimated percentage with defect:** 100%

### Vehicle Information

**Vehicle 1:** 2026-2026 Hyundai Translead 30023338

**Product Category:**

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Apr 01, 2025 - Apr 01, 2025

**Number of potentially involved:** 2

#### Descriptive Information:

Hiab USA Inc. ("Hiab") has decided that certain Waltco-branded ZS series slide liftgates imported from Z-Lyften Produktion AB may contain a safety-related defect involving the cylinder-pivot pin. Accordingly, Hiab is conducting a voluntary safety recall. The affected liftgates are heavy-duty slide lifts with a single-folding platform designed for installation on trailers and semi-trailers. Hyundai Translead installed two of these slide liftgates in units 3H3V452KXTJ446801 and 3H3V452K1TJ446802 belonging to BOM # 30023338.

### Defect / Noncompliance Description

#### Description of the defect or noncompliance:

On affected liftgates, the cylinder-pivot pin may not have had adequate lubricant penetration during manufacturing. Cylinder-pivot pins with limited lubrication can in some circumstances result in the pin seizing in the bore, potentially causing the liftgate to malfunction or to fail under a load, which increases the risk of injury to the operator.

**FMVSS1:**

**FMVSS2:**

# Part 573 Safety Recall Report

**25V331****Description of the safety risk, including crash, fire, death, injury:**

Insufficient lubrication may cause the lift cylinder pin to seize, potentially causing the liftgate to malfunction or fail under the load.

**Description of the cause:****Identification of any warning that can occur:**

## Component Manufacturer

**Tier of Supplier:** Tier 1**Supplier Type:** OEM**Name:** Hiab USA Inc.**Address:** 1777 Miller Parkway  
Streetsboro OH, 44241**Country:** United States

## Involved Components

**Component Name 1:** Waltco Model No.: ZS-33**Component Description:** Heavy-duty slide lifts with a single-folding platform**Component Part Number:** ZS-MK2SLI 2000-155**Component Name 2:** Waltco Model No.: ZS-44**Component Description:** Heavy-duty slide lifts with a single-folding platform**Component Part Number:** ZS-MK2STD 2000-155)

## Chronology

Hyundai Translead was notified 5/19/2025 that Hiab USA Inc. ("Hiab") had decided that certain Waltco-branded ZS series slide liftgates imported from Z-Lyften Produktion AB may contain a safety-related defect involving the cylinder-pivot pin. Accordingly, Hiab is conducting a voluntary safety recall. We received a letter from them because their records show that we received two liftgates that may be affected and we installed in two of our units. In turn, we notified customer 5/21/2025.

# Part 573 Safety Recall Report

# 25V331

Related NHTSA Recall Number: 25E025

## Description of Remedy

**Remedy Type:** Replace

**Consumer Advisories:** ☒ Do Not Drive ☐ Park Outside

**Description of remedy program:**

Hiab has released a redesigned lift cylinder pin with integrated grease ports. The original lift cylinder pins must be replaced by the redesigned pins with grease zerk and channels for the liftgates identified in the Safety and Repair Instructions file provided by Hiab.

**How remedy component differs from recalled component:**

The redesigned lift cylinder pin has integrated grease ports unlike the recalled lift cylinder pin.

**Identify how/when recall condition was corrected in production:**

Hyundai Translead was notified 5/19/2025 that Hiab USA Inc. ("Hiab") had decided that certain Waltco-branded ZS series slide liftgates imported from Z-Lyften Produktion AB may contain a safety-related defect involving the cylinder-pivot pin. Accordingly, Hiab is conducting a voluntary safety recall. We receiving a letter from them because their records show that we received two liftgates that may be affected.

## Reimbursement Plan

**Description of reimbursement program:**

Normal warranty procedures apply in this matter. Claims should be submitted to Warranty Claims online at [www.waltcoliftgates.com](http://www.waltcoliftgates.com).

**Period of reimbursement:**

All warranty claims related to this campaign must be submitted to Hiab-Waltco warranty department within six months of the date of the repair.

**Costs to be reimbursed:**

The replacement of the two lift cylinder pins will be compensated with 1.5 working hours per liftgate. If the pins are seized, an additional 30 minutes per seized pin will be authorized. If additional time is required to complete the remedy, contact Waltco Warranty for supplemental labor authorization.

**Address for reimbursement claims:**

1777 Miller Parkway  
Streetsboro OH, 44241

## Recall Schedule

# Part 573 Safety Recall Report

**25V331****Description of recall schedule:**

Hyundai Translead was notified 5/19/2025 that Hiab USA Inc. ("Hiab") had decided that certain Waltco-branded ZS series slide liftgates imported from Z-Lyften Produktion AB may contain a safety-related defect involving the cylinder-pivot pin. Accordingly, Hiab is conducting a voluntary safety recall. We received a letter from Hiab as well as the remedy because their records show that we received two liftgates that may be affected and we installed on two of our units. In turn, Hyundai Translead reached out to customer with provided remedy 5/21/2025.

**Planned Dealer Notification Date:**☒ No Dealers**Planned Interim Owner Notification Date:** May 21, 2025 - May 21, 2025☐ No Owners**Planned Remedy Owner Notification Date:** May 21, 2025 - May 21, 2025☐ Phased Recall**Date when VIN will be searchable:** May 21, 2025