



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

## Part 573 Safety Recall Report

## 25V451

**Manufacturer Name:** Autocar, LLC

**Submission Date:** Jul 03, 2025

**NHTSA Recall No.:** 25V451

**Manufacturer Recall No.:** ACTT-2504

### Manufacturer Information

### Population

**Manufacturer Name:** Autocar, LLC

**Address:** 551 S WASHINGTON  
STREET  
HAGERSTOWN IN, 47346

**Total number of potentially involved:** 195

**Estimated percentage with defect:** 100%

### Vehicle Information

**Vehicle 1:** 2012-2025 AUTOCAR XSPOTTER

**Product Category:** Buses, Medium & Heavy Vehicles

**Product Type:** Tractor

**Fuel / Propulsion:**

**Production Dates:** Dec 01, 2011 - Apr 09, 2025

**Number of potentially involved:** 195

**Descriptive Information:**

All Xspotter vehicles with incorrect tire inflation labels are included.

### Defect / Noncompliance Description

**Description of the defect or noncompliance:**

The tire inflation labels have a 0-pressure value

**FMVSS1:** 110 - Tire selection and rims

**FMVSS2:**

**Description of the safety risk, including crash, fire, death, injury:**

These vehicles fail to comply with 49CFR 571.110 and operating the vehicle with under inflated tires can increase the risk of a crash.

**Description of the cause:**

# Part 573 Safety Recall Report

**25V451**

A manufacturing error resulted in the tire inflation labels being miss-printed.

**Identification of any warning that can occur:**

None

## Component Manufacturer

**Tier of Supplier:**

**Supplier Type:** OEM

**Name:** Autocar

**Address:** 551 S Washington St  
Hagerstown IN, 47346

**Country:** United States

## Involved Components

**Component Name 1:** Autocar Tire Inflation Label

**Component Description:** Tire Inflation Label

**Component Part Number:** A9710004-001

## Chronology

May 8, 2025, Autocar personnel identified a miss printed tire inflation label, June 4, 2025, through June 25, 2025, second miss printed label was identified and an internal investigation was performed. June 26, 2025., all relevant information was presented to Autocar's management team and Autocar decided to perform a voluntary safety recall. We have no known cases complaints or claims.

**Related NHTSA Recall Number:**

## Description of Remedy

**Remedy Type:** Mail Information/Labels

**Consumer Advisories:** ☐ Do Not Drive ☐ Park Outside

**Description of remedy program:**

# Part 573 Safety Recall Report

# 25V451

Autocar will voluntarily initiate an owner notification and recall of all affected vehicles. Autocar will distribute to owners of affected vehicles an Owner Notification Letter, which will describe the defect and provide instructions for scheduling the inspection/repair of the vehicle at no cost to the vehicle's owner. The owner letter will instruct vehicle owners who have paid to have this condition remedied prior to this campaign to seek reimbursement pursuant to Autocar's General Reimbursement Plan, on file with the agency pursuant to 49 C.F.R. 573.6(c)(8)(i) and 49 C.F.R 573.13.

## How remedy component differs from recalled component:

The labels will be properly printed and include the tire inflation information.

## Identify how/when recall condition was corrected in production:

The tire inflation label information has been updated and a clean point established for production June 25, 2025.

## Reimbursement Plan

Manufacturer used general reimbursement plan on file.

## Recall Schedule

### Description of recall schedule:

The dealer and owner notifications will begin September 29, 2025, and end August 1, 2025.

**Planned Dealer Notification Date:** Aug 29, 2025 - Sep 01, 2025 ☐ No Dealers

**Planned Interim Owner Notification Date:** ☐ No Owners

**Planned Remedy Owner Notification Date:** Aug 29, 2025 - Sep 01, 2025 ☐ Phased Recall

**Date when VIN will be searchable:** Sep 01, 2025