

Part 573 Safety Recall Report

19V-166

Manufacturer Name : Jayco, Inc.**Submission Date :** MAR 05, 2019**NHTSA Recall No. :** 19V-166**Manufacturer Recall No. :** 9901431**Manufacturer Information :**

Manufacturer Name : Jayco, Inc.

Address : 903 South Main Street

PO Box 460 Middlebury IN 46540

Company phone : 800-283-8267

Population :

Number of potentially involved : 13

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2019-2019 Jayco Fifth Wheel North Point 387RDFS "LZ"

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : POs from supplier with specific date range matched to production dates - Units produced after 9/14/18 supplier had a design changed to the rivets of the cargo tray - not affected

2019 North Point Fifth Wheel
K1LZ0050-0062

Production Dates : JUN 29, 2018 - JUL 16, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : Per supplier - Rivets securing the stop bracket to the cargo tray have insufficient strength and can shear causing the stop brackets to separate and allow the tray to be pulled out and fall to ground

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Risk of personal injury to consumer if drawer pulls all the way out of the frame.

Description of the Cause : Rivets originally specified are hollow rivets of insufficient strength

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : MorRyde International
Address : 1966 Sterling Ave
Elkhart INDIANA 46516
Country : United States

Chronology :

2-20-19 Recevd email from MorRyde noting upcoming recall on specific models of Cargo Trays - Notification included list of POs delivered to Jayco that noted the affected trays - information matched to Corp Purchasing records that trays were purchased for 2019 North Point fifth wheels production line- production records reviewed for affected product serial numbers. and scope was created 2-28-19 Safety Committee reviewed all details and decided that a Recall is required.

Description of Remedy :

Description of Remedy Program : Jayco Dealers will remove the original hollow rivets and replace with structural rivets at no charge to current owner. 4 rivets per tray

How Remedy Component Differs from Recalled Component : Original rivet - Steel hollow rivet .188x.236-335
Replacement rivet - Stainless Steel grip structural .188x.236-.335

Identify How/When Recall Condition was Corrected in Production : During MorRyde regular design review of their products - decision was made to strengthen the rivets in the stop bracket of two models of Cargo Trays CTG60-48115W and CTG60-48105W -

Recall Schedule :

Description of Recall Schedule : Jayco will notify current owners (Dlr Rtl) upon receipt of recall # assigned by NHTSA

Planned Dealer Notification Date : MAR 20, 2019 - MAR 20, 2019

Planned Owner Notification Date : MAR 20, 2019 - MAR 20, 2019

* NR - Not Reported