

Part 573 Safety Recall Report

19V-205

Manufacturer Name : QUALITY VAN SALES, INC.

Submission Date : MAR 17, 2019

NHTSA Recall No. : 19V-205

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : QUALITY VAN SALES, INC.

Address : 349 OLD COLONY ROAD

NORTON MA 02766

Company phone : 800-408-8550

Population :

Number of potentially involved : 471

Estimated percentage with defect : 10 %

Vehicle Information :

Vehicle 1 : 2015-2018 Ford vans econolines and transits

Vehicle Type : LIGHT VEHICLES

Body Style : VAN

Power Train : GAS

Descriptive Information : Freedman seats GO-ES FOLDAWAY SEAT back cushion may not lock into place properly and not support the occupant in case of a crash situation.

Production Dates : FEB 24, 2015 - JUL 10, 2018

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : seat back mechanism may malfunction

FMVSS 1 : 207 - Seating systems

FMVSS 2 : NR

Description of the Safety Risk : may cause occupant injury in case of accident

Description of the Cause : back frame weldment is too narrow

Identification of Any Warning that can Occur : back cushion may not lock in properly and not support the occupant in event of a crash

Supplier Identification :

Component Manufacturer

Name : Freedman Seating

Address : 4545 W. Augusta Blvd

Chicago ILLINOIS 60651

Country : United States

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported