

Floyd Vest - Comments

SAE-02 is inherently unsafe and should be eliminated except for experimental use with an engineering monitoring to warn of imminent program failure. Without this you are placing a lulled driver into an emergency situation, a recipe for disaster. Also, while it is not politically correct, SAE-06 is obviously missing and any plan for automating trucking should include plans for creating jobs for displaced drivers, our nation's number one occupation.