

Part 573 Safety Recall Report

19V-623

Manufacturer Name : Lance Camper Manufacturing, Corp.**Submission Date :** AUG 26, 2019**NHTSA Recall No. :** 19V-623**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :**

Manufacturer Name : Lance Camper Manufacturing, Corp.

Number of potentially involved : 151

Address : 43120 Venture Street

Estimated percentage with defect : 35 %

Lancaster CA 93535

Company phone : 661-949-3322

Vehicle Information :

Vehicle 1 : 2018-2019 Lance Camper 2018 / 2019 855S

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : 12 Volt battery power and or ground wire can come in contact with the hot burner box of the refrigerator

Production Dates : JAN 03, 2018 - JAN 18, 2019

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential**Description of Defect :**

Description of the Defect : 12 Volt battery power and or ground wire can come in contact with the hot burner box of the refrigerator

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The insulation on the wire can melt causing the wire to short out on the refrigerator burner box and could cause fire

Description of the Cause : NR

Identification of Any Warning : Only warning would be a visible inspection that can Occur :

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR
NR
Country : NR

Chronology :

08/14/2019 Received email with pictures of a camper with burnt refrigerator wiring showing the issue

08/16/2019 Visited a local dealership to examine two of the possible affected units one was ok the other could be a problem.

8/21/19 Determination of a defect by safety committee

Description of Remedy :

Description of Remedy Program : Lance camper will notify the owners and dealers of a potential issue. Dealers will install a clamp to secure the wire. This service will be free of charge.

How Remedy Component Differs from Recalled Component : Clamp installed on the floor of the refrigerator cabinet securing the 12 volt wires.

Identify How/When Recall Condition was Corrected in Production : Implementing a design change in Jan. 2019. Manufacturing had requested an Engineer change to the wire routing. This change routed the wires away from the refrigerator/ burner box.

Recall Schedule :

Description of Recall Schedule : We will notify Owners and Dealers during October 2019

Planned Dealer Notification Date : OCT 14, 2019 - OCT 18, 2019

Planned Owner Notification Date : OCT 14, 2019 - OCT 18, 2019

* NR - Not Reported