

Part 573 Safety Recall Report

19V-747

Manufacturer Name : Forest River, Inc.

Submission Date : OCT 18, 2019

NHTSA Recall No. : 19V-747

Manufacturer Recall No. : 55-1105



Manufacturer Information :

Manufacturer Name : Forest River, Inc.

Address : 55470 CR 1

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 1-800-348-7440

Population :

Number of potentially involved : 14

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2017-2017 Forest River, Inc. Dynamax - DXC37BH, DXC37RB, DXC37TS, FRC37BHHD & FRC37TSHD

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On October 18, 2019, Forest River was able to identify population using the VINs provided by Detroit Diesel.

DYNAMAX DX3 - DXC37BH - 1

DYNAMAX DX3 - DXC37RB - 3

DYNAMAX DX3 - DXC37TS - 5

DYNAMAX FORCE - FRC37BHHD - 3

DYNAMAX FORCE - FRC37TSHD - 2

Production Dates : NOV 20, 2017 - JAN 30, 2018

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Description of Defect :

Description of the Defect : According to the Detroit Diesel defect notice: "A different I-beam design was introduced on Model 3 Detroit™ Axles that does not have a flat mating surface on the bottom side of the I-beam where the optional stabilizer brackets are mounted and may result in damage to the stabilizer bracket due to bending stress during assembly of the U- bolts at the truck manufacturing plant."

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the stabilizer bracket broke, there may be a loss of vehicle control which may lead to a crash.

Description of the Cause : None provided

Identification of Any Warning that can Occur : None provided

Supplier Identification :

Component Manufacturer

Name : Detroit Diesel
Address : 13400 Outer Drive, West
Detroit MICHIGAN 48239-4001
Country : United States

Chronology :

On October 15, 2019, Forest River was notified of this pass through recall.
On October 18, 2019, Forest River was able to identify population.

Detroit Diesel will be responsible for reporting.

Description of Remedy :

Description of Remedy Program : According to the Detroit Diesel defect notice: "Please contact a Detroit Diesel Authorized Repair Facility to arrange to have the Field Action performed. To locate an authorized facility, search online at www.detroitdiesel.com/locations/default.aspx This service will be completed for you at no charge, prior to September 26, 2020, under the provisions of this notice."

How Remedy Component Differs from Recalled Component : None provided

Identify How/When Recall Condition was Corrected in Production : None provided

Recall Schedule :

Description of Recall Schedule : Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : NOV 27, 2019 - NOV 27, 2019

Planned Owner Notification Date : NOV 27, 2019 - NOV 27, 2019

* NR - Not Reported