

# Part 573 Safety Recall Report

# 19V-871

**Manufacturer Name :** Proterra Inc.**Submission Date :** DEC 09, 2019**NHTSA Recall No. :** 19V-871**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Proterra Inc.

Address : 1815 Rollins Road  
Burlingame CA 94010

Company phone : 4380000

**Population :**

Number of potentially involved : 151

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2019-2019 Proterra Catalyst

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

**Descriptive Information :** Parking brake engagement warnings (lights and sound) were disabled unintentionally on certain Catalyst vehicles after a July 23, 2019 software update. Unaware drivers may be allowed to drive with the rear brake interlock engaged which could cause the rear brakes to overheat, damaging the vehicle.

Production Dates : JUL 23, 2019 - DEC 02, 2019

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

**Description of the Defect :** A body controller software update was made to certain Proterra Catalyst vehicles on July 23, 2019 that contained a bug that in certain circumstances, disabled both audible and visible warnings that the brake interlock could be engaged. This circumstance occurs when the driver shifts the vehicle to neutral and then switches the HV master switch on the dash to off, without out first manually engaging the parking brake. In this scenario, the vehicle controller engages the rear brake interlock to prevent the vehicle from rolling. If the vehicle HV system is switched back on, the rear brake interlock remains engaged and the vehicle does not provide a warning to the driver. At this point it is possible to drive the vehicle away with the rear brake interlock engaged causing the rear brakes to overheat.

FMVSS 1 : NR

FMVSS 2 : NR

**Description of the Safety Risk :** The potential for the rear brakes to overheat during vehicle operation if the

**Description of the Safety Risk :** brake interlock drag is not detected by the driver.

**Description of the Cause :** A software update unintentionally disabled the brake interlock warnings if the vehicle is turned off without setting the parking brake.

**Identification of Any Warning that can Occur :** The defect prevents audible and visible warning to the driver that the interlock brake is engaged. The driver may notice that the rear brakes are dragging but does not see or hear the normal warning.

## Supplier Identification :

### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

## Chronology :

On November 7, 2019, a customer reported that the rear brakes on an off-duty bus had “locked up” while driving. Proterra’s field service team investigated and notified the company’s safety committee. The Safety Committee Chairperson ordered an immediate investigation of the incident on November 7, 2019.

On November 14, 2019 a second customer reported a similar issue.

On November 19, 2019 and November 22, 2019, the Safety Committee met to review the matter and to expand the November 7th investigation.

On November 26, 2019, an additional customer reported a similar issue.

As a result of the investigation, on December 2, 2019, the Safety Committee concluded that the driver error of driving the bus with the brake engaged was related to a software update in July 2019 that inadvertently disabled the audible and visual warning systems that alerted drivers that the parking brake system was engaged. The Committee determined that a recall would be issued.

## Description of Remedy :

**Description of Remedy Program :** Proterra will update software on all affected vehicles at no cost to the customer. Driver will always have visual and audible indication that the brake interlock is set when they are attempting to drive.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : The recall condition was corrected with a software update in production that was implemented on 12/4/2019.

### Recall Schedule :

Description of Recall Schedule : Proterra does not have any dealers and sells directly to customers. All letters will go out at the same time.

Planned Dealer Notification Date : JAN 09, 2020 - JAN 09, 2020

Planned Owner Notification Date : JAN 09, 2020 - JAN 09, 2020

\* NR - Not Reported