

# Part 573 Safety Recall Report

# 20V-133

**Manufacturer Name :** Corp. Micro Bird Inc.

**Submission Date :** MAR 06, 2020

**NHTSA Recall No. :** 20V-133

**Manufacturer Recall No. :** 20-084-RUS



## Manufacturer Information :

**Manufacturer Name :** Corp. Micro Bird Inc.

**Address :** 3000, Rue Girardin

Drumondville, Quebec 00 J2E 0A1

**Company phone :** 819-477-2012

## Population :

**Number of potentially involved :** 17,693

**Estimated percentage with defect :** 100 %

## Vehicle Information :

**Vehicle 1 :** 2004-2021 Micro Bird T-Series, G5 and MBII

**Vehicle Type :**

**Body Style :**

**Power Train :** NR

**Descriptive Information :** The rear emergency door retaining device may prematurely stop functioning properly

**Production Dates :** NOV 02, 2004 - MAR 02, 2020

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

## Description of Noncompliance :

**Description of the Noncompliance :** The rear emergency door retaining device may prematurely stop working properly

**FMVSS 1 :** 217 - Bus emergency exits and window retention and release

**FMVSS 2 :** NR

**Description of the Safety Risk :** The rear emergency door retaining device may break apart and/or stop retaining the emergency door in the open position, which may cause the door to close during emergency evacuation of the vehicle

**Description of the Cause :** NR

**Identification of Any Warning that can Occur :** NR

## Supplier Identification :

### Component Manufacturer

**Name :** NR

Address : NR  
NR  
Country : NR

**Chronology :**

After a visit to a school bus operator facility, NHTSA informed Micro Bird that the rear emergency door retaining device of an inspected bus was malfunctioning. After further analysis of the retaining device, as well as inquiries about warranty claims and after-warranty purchases of the parts, it was determined that the part may prematurely, or under certain circumstances, stop functioning correctly. Accordingly, it was decided on February 28, 2020 to recall the vehicles equipped with the identified rear emergency door retaining device

**Description of Remedy :**

Description of Remedy Program : NR  
How Remedy Component Differs from Recalled Component : NR  
Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : Micro Bird will provide instructions and repair kits with no charge. It will be the responsibility of the bus owners to execute the mitigation  
Planned Dealer Notification Date : MAR 27, 2020 - APR 10, 2020  
Planned Owner Notification Date : APR 17, 2020 - MAY 01, 2020

\* NR - Not Reported