

# Part 573 Safety Recall Report

## 20V-311

**Manufacturer Name :** Keystone RV Company**Submission Date :** MAY 28, 2020**NHTSA Recall No. :** 20V-311**Manufacturer Recall No. :** 20-378**Manufacturer Information :****Population :**

Manufacturer Name : Keystone RV Company

Number of potentially involved : 9

Address : PO Box 2000  
2642 Hackberry Drive Goshen IN  
46527

Estimated percentage with defect : 100 %

Company phone : 574-535-2100

**Vehicle Information :**

Vehicle 1 : 2020-2020 Keystone Springdale 295BHWE

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : 295BHWE model

Production Dates : FEB 10, 2020 - MAR 16, 2020

VIN Range 1 : Begin : 4YDT29525LG105132 End : 4YDT29522LG108523 ☒ Not sequential**Description of Defect :**

Description of the Defect : It has been decided that the vehicles in the recall population fail to conform to the requirements of Part 567, "Certification." The vehicles subject to this recall may have been manufactured with the incorrect information on the Federal Identification Tag. The tag indicates the load range in the tire size is ST255/75R15E @ 80 psi. The correct load range is LRD, tire size is ST255/75R15D @ 65 psi. This does not affect the GVWR just the tire data.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Fails to conform to the requirements of Part 567, "Certification." An incorrect label may lead to unintentionally overinflating or overloading the tires, increasing the risk of a crash.

Description of the Cause : The incorrect load range and psi were printed on the label.

Identification of Any Warning that can Occur : The tire size and PSI rating on the Federal Identification Tag do not match the information for the tire and rim.

**Involved Components :**

Component Name 1 : Fed Tag

Component Description : Label - Tread Gen Fed Cert Combo Laser - 9/05 - FD316

Component Part Number : 192406

### Supplier Identification :

#### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

### Chronology :

5/13/2020 – Dealer states that the tires are incorrect on 4YDT29520LG108522, tires are ST225/75R15D @ 65psi and the Federal Identification Tag states ST225/75R15E @ 80psi. Investigation opened to inspect units to verify information.

5/21/2020 – Investigation concluded, range and scope completed. Determined that the Federal Identification Tag would need to be replaced.

### Description of Remedy :

Description of Remedy Program : The remedy is to replace the Federal Identification Tag. Manufacturer Reimbursement Plan on file as of 10/25/2018. General reimbursement plan to be updated every two years. New vehicles are covered under warranty.

How Remedy Component Differs from Recalled Component : The replacement of the Federal Identification Tag, Keystone Part # 192406 - Label - Tread Gen Fed Cert Combo Laser - 9/05 - FD316, will conform to requirements of Part 567, "Certification."

Identify How/When Recall Condition was Corrected in Production : Units were quarantined, inspected then repaired as indicated by inspection.

### Recall Schedule :

Description of Recall Schedule : Keystone will notify the dealers and owners of the recreational vehicles

by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.

Planned Dealer Notification Date : JUL 27, 2020 - JUL 27, 2020

Planned Owner Notification Date : JUL 27, 2020 - JUL 27, 2020

\* NR - Not Reported