

Part 573 Safety Recall Report

20V-656

Manufacturer Name : Forest River, Inc.

Submission Date : OCT 26, 2020

NHTSA Recall No. : 20V-656

Manufacturer Recall No. : 400-1243



Manufacturer Information :

Manufacturer Name : Forest River, Inc.

Address : 55470 CR 1

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 1-800-348-7440

Population :

Number of potentially involved : 1,150

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2019-2021 Forest River Inc. Palomino - PAT240BHS-W, PAT249RBS, PAT249RBS-W, PAT253RLS, PAT253RLS-W, PAT258RBSS, PAT258RBSS-W, PAT260FKBS, PAT260FKBS-W, PAT268BHSK, PAT268BHSK-W, PAT292QBSK, PAT292QBSK-W, PAT304RKDS, PAT304RKDS-W, PAT312TSQBK, PAT314TSBH, PAT314TSBH-W, PAT316RLTS

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : The manufacturing plant was able to identify the vehicles affected by using purchasing records from when this model of antenna was put into production.

PALOMINO	PAT240BHS-W2019	2
PALOMINO	PAT240BHS-W2020	7
PALOMINO	PAT240BHS-W2021	15
PALOMINO	PAT249RBS 2020	15
PALOMINO	PAT249RBS-W 2020	1
PALOMINO	PAT249RBS-W 2021	1
PALOMINO	PAT253RLS 2020	34
PALOMINO	PAT253RLS 2021	7
PALOMINO	PAT253RLS-W 2020	6
PALOMINO	PAT253RLS-W 2021	1
PALOMINO	PAT258RBSS 2020	28
PALOMINO	PAT258RBSS 2021	54
PALOMINO	PAT258RBSS-W 2020	2
PALOMINO	PAT258RBSS-W 2021	4
PALOMINO	PAT260FKBS 2020	70
PALOMINO	PAT260FKBS 2021	45
PALOMINO	PAT260FKBS-W 2020	10
PALOMINO	PAT260FKBS-W 2021	8
PALOMINO	PAT268BHSK 2020	21
PALOMINO	PAT268BHSK 2021	30
PALOMINO	PAT268BHSK-W 2020	4
PALOMINO	PAT268BHSK-W 2021	5
PALOMINO	PAT292QBSK 2020	11
PALOMINO	PAT292QBSK 2021	2
PALOMINO	PAT292QBSK-W 2020	5
PALOMINO	PAT292QBSK-W 2021	3
PALOMINO	PAT304RKDS 2020	42
PALOMINO	PAT304RKDS 2021	36
PALOMINO	PAT304RKDS-W 2021	3
PALOMINO	PAT312TSQBK 2019	1
PALOMINO	PAT314TSBH 2019	1
PALOMINO	PAT314TSBH-W 2020	1
PALOMINO	PAT316RLTS 2020	33
PALOMINO	PAT316RLTS 2021	34
PALOMINO	PAT316RLTS-W 2020	2

Production Dates : SEP 09, 2019 - OCT 19, 2020

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 2 : 2019-2021 Forest River Inc. Palomino - PAT316RLTS-W, PAT317BHSK, PAT317BHSK-W, PAT319DQBH, PAT320TSBH, PAT320TSBH-W, PATEV-1, PATEV-1-W, PAT-2-W, PATEV-3, PAT-3-W

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : The manufacturing plant was able to identify the vehicles affected by using purchasing records from when this model of antenna was put into production.

PALOMINO	PAT316RLTS-W	2020	2
PALOMINO	PAT316RLTS-W	2021	1
PALOMINO	PAT317BHSK	2019	1
PALOMINO	PAT317BHSK	2020	12
PALOMINO	PAT317BHSK	2021	16
PALOMINO	PAT317BHSK-W	2020	3
PALOMINO	PAT319DQBH	2021	1
PALOMINO	PAT320TSBH	2020	55
PALOMINO	PAT320TSBH	2021	51
PALOMINO	PAT320TSBH-W	2020	1
PALOMINO	PATEV-1	2020	1
PALOMINO	PATEV-1	2021	10
PALOMINO	PATEV-1-W	2021	9
PALOMINO	PATEV-2-W	2021	1
PALOMINO	PATEV-3	2021	8
PALOMINO	PATEV-3-W	2021	3

Production Dates : SEP 09, 2019 - OCT 19, 2020

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 3 : 2019-2021 Forest River Inc. Palomino - PAT147X, PAT147X-W, PAT163X, PAT163X-W, PAT183RDB, PAT184, PAT185X, PAT185X-W, PAT186, PAT186RBS-W, PAT186-W, PAT189, PAT189BHS, PAT189BHS-W, PAT189-W, PAT202RB, PAT202RB-W, PAT205SS, PAT205SS-W, PAT217BH, PAT217BH-W, PAT240BHS, PAT240BHS-W

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : The manufacturing plant was able to identify the vehicles affected by using purchasing records from when this model of antenna was put into production.

PALOMINO	PAT147X	2020	4
PALOMINO	PAT147X	2021	14
PALOMINO	PAT147X-W	2020	3
PALOMINO	PAT147X-W	2021	9
PALOMINO	PAT163X	2020	2
PALOMINO	PAT163X	2021	13
PALOMINO	PAT163X-W	2020	3
PALOMINO	PAT163X-W	2021	12
PALOMINO	PAT183RDB	2020	3
PALOMINO	PAT184	2021	1
PALOMINO	PAT185X	2020	5
PALOMINO	PAT185X	2021	13
PALOMINO	PAT185X-W	2020	6
PALOMINO	PAT186	2021	31
PALOMINO	PAT186RBS	2021	6
PALOMINO	PAT186RBS-W	2021	3
PALOMINO	PAT186-W	2021	4
PALOMINO	PAT189	2021	29
PALOMINO	PAT189BHS	2021	5
PALOMINO	PAT189BHS-W	2021	3
PALOMINO	PAT189-W	2021	8
PALOMINO	PAT202RB	2020	20
PALOMINO	PAT202RB	2021	20
PALOMINO	PAT202RB-W	2020	5
PALOMINO	PAT202RB-W	2021	5
PALOMINO	PAT205SS	2020	40
PALOMINO	PAT205SS	2021	53
PALOMINO	PAT205SS-W	2020	5
PALOMINO	PAT205SS-W	2021	9
PALOMINO	PAT217BH	2020	18
PALOMINO	PAT217BH	2021	20
PALOMINO	PAT217BH-W	2020	10
PALOMINO	PAT217BH-W	2021	4
PALOMINO	PAT240BHS	2020	11
PALOMINO	PAT240BHS	2021	36

Production Dates : SEP 09, 2019 - OCT 19, 2020

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : The antenna wing on the roof may not be secured properly, which could cause the antenna wing to come unattached from the roof while the vehicle is in transit.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the antenna comes unattached from the vehicle, it can cause property damage, or injury.

Description of the Cause : The wires for the antenna were not pulled through all the way which causes the antenna's wing to not snap into place allowing it to possibly come unattached from the vehicle.

Identification of Any Warning that can Occur : None

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

On 10/19/2020 The manufacturing plant received information regarding an antenna that had come off a travel trailers roof and impacted a vehicles windshield.

On 10/20/2020 The manufacturing plant inspected all vehicles in Forest River's possession for this concern and found that the wires for the antenna were causing the antenna wing not to seat properly on the base.

On 10/23/2020 Forest Rivers Corporate Recall Committee voted to recall

Description of Remedy :

Description of Remedy Program : Forest River will provide all parts and labor to inspect, repair or replace the antenna. An authorized Forest River dealer or service center will need to perform the repairs

What is the Forest River Customer Service Phone Number? (269)
432-3271

How Remedy Component Differs from Recalled Component : The antenna wing will be properly secured to the base.

Identify How/When Recall Condition was Corrected in Production : The week of 10/19/2020, The wiring is now being pulled all the way through and down in order for enough clearance to allow the antenna wing to seat properly on the base.

Recall Schedule :

Description of Recall Schedule : Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : DEC 02, 2020 - DEC 02, 2020

Planned Owner Notification Date : DEC 02, 2020 - DEC 02, 2020

* NR - Not Reported