

# Part 573 Safety Recall Report

# 21V-147

**Manufacturer Name :** Chrysler (FCA US, LLC)**Submission Date :** MAR 09, 2021**NHTSA Recall No. :** 21V-147**Manufacturer Recall No. :** Y11**Manufacturer Information :**

Manufacturer Name : Chrysler (FCA US, LLC)

Address : 800 Chrysler Drive  
CIMS 482-00-91 Auburn Hills MI  
48326-2757

Company phone : 1-800-853-1403

**Population :**

Number of potentially involved : 4

Estimated percentage with defect : 1 %

**Vehicle Information :**

Vehicle 1 : 2020-2021 Ram ProMaster City

Vehicle Type :

Body Style : VAN

Power Train : NR

**Descriptive Information :** Some 2020-2021 MY Ram ProMaster City vehicles may have been built with an antilock braking system module ("ABS module") with a damaged damper membrane.

The suspect period began on August 15, 2020, when the first vehicle produced for the US market was built with a suspect ABS module, and ended on October 6, 2020, when the last vehicle produced for the US market was built with a suspect ABS module. The suspect period was determined using supplier and vehicle production traceability records.

Similar vehicles not included in this recall were built before or after the suspect period or are not equipped with a suspect ABS module.

Production Dates : AUG 15, 2020 - OCT 06, 2020

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

**Description of the Defect :** A damaged damper membrane within the ABS module may result in the loss of autonomous braking functionalities and a reduction in the braking performance.

FMVSS 1 : NR

FMVSS 2 : NR

**Description of the Safety Risk :** The loss of autonomous braking functionalities and loss in braking performance can cause vehicle crash without prior warning.

**Description of the Cause :** NR

Identification of Any Warning NR  
that can Occur :

## Involved Components :

Component Name 1 : Antilock Braking System Module

Component Description : ABS module

Component Part Number : 68333306AA

## Supplier Identification :

### Component Manufacturer

Name : CONTINENTAL TEVES AG & CO OHG

Address : Guerickestrasse 7  
Frankfurt am Main Foreign States 60488

Country : Germany

## Chronology :

- On February 8, 2021, FCA Italy was informed by the supplier about a potential issue regarding the ABS module.
- On February 9, 2021, FCA Italy Quality began analyzing assembly production records and supplier information to determine the scope of vehicles potentially affected.
- As of March 2, 2021, FCA US LLC ("FCA US") has identified zero customer assistance records, zero warranty claims, and zero field reports potentially relating to this issue.
- As of March 2, 2021, FCA US is not aware of any accidents or injuries potentially relating to this issue.
- On March 2, 2021, FCA Italy determined, through the Vehicle Regulations Committee, to conduct a voluntary safety recall of the affected vehicles.

## Description of Remedy :

Description of Remedy Program : FCA US will conduct a voluntary safety recall on all affected vehicles to replace the ABS module.

FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.

How Remedy Component Differs from Recalled Component : The remedy component will be an ABS module that utilizes the supplier's new programming process and verification controls.

Identify How/When Recall Condition was Corrected in Production : NR

## Recall Schedule :

Description of Recall Schedule : \*\*03/09/2021: FCA US will notify dealers and begin notifying owners on or about 04/28/2021.

Planned Dealer Notification Date : APR 28, 2021 - APR 28, 2021

Planned Owner Notification Date : APR 28, 2021 - APR 28, 2021

\* NR - Not Reported