

Part 573 Safety Recall Report

21V-566

Manufacturer Name : Shyft Group**Submission Date :** JUL 26, 2021**NHTSA Recall No. :** 21V-566**Manufacturer Recall No. :** 21-18**Manufacturer Information :****Manufacturer Name :** Shyft Group**Address :** 1541 Reynolds Road
Charlotte MI 48813**Company phone :** 517-543-6400**Population :****Number of potentially involved :** 309**Estimated percentage with defect :** 100 %**Vehicle Information :****Vehicle 1 :** 2021-2022 Spartan RV Chassis K2 and K3**Vehicle Type :** BUSES, MEDIUM & HEAVY VEHICLES**Body Style :** OTHER**Power Train :** DIESEL**Descriptive Information :** The basis for the recall population is a list of engine serial numbers, for 2021 L9 engines, supplied by Cummins as it relates to recall 20E-063. The engine serial numbers were crossed reference to establish the list of VIN's.**Production Dates :** OCT 13, 2020 - JUL 20, 2021**VIN Range 1 : Begin :**

NR

End : NR☐ Not sequential**Description of Defect :****Description of the Defect :** A fuel leak may occur in the fuel hoses between the fuel pump and the remote fuel filter head.**FMVSS 1 :** NR**FMVSS 2 :** NR**Description of the Safety Risk :** A fuel leak in the presence of an ignition source may increase the risk of a fire.**Description of the Cause :** Inadequate design and quality of the fuel hose assembly.**Identification of Any Warning that can Occur :** Persons operating in or around the vehicle may see smoke before sufficient heat creates a fire.**Involved Components :**

Component Name 1 : Fuel Hose

Component Description : Fuel carrying hose with quick connect fittings

Component Part Number : 5563641, 5563642, and 5563643

Supplier Identification :

Component Manufacturer

Name : Cummins, Inc.

Address : 301 Washington Street

P.O. Box 3005, Mail Code 91630 Columbus Indiana 47202

Country : United States

Chronology :

On July 19, 2021, Shyft received notice of recall 21E-063 from Cummins along with an engine serial number list. On July 20, 2021 Shyft began cross referencing the engine serial numbers to vehicle identification numbers. On July 21, 2021, Shyft issued a stop ship on chassis still in it's possession and on July 22, 2021, Shyft determined that a defect related to motor vehicle safety could exist in the remaining chassis.

Description of Remedy :

Description of Remedy Program : Cummins will supply new fuel hoses. The affected chassis, and their engines, are still within their warranty period therefore any reported failure would likely be covered under warranty.

How Remedy Component Differs from Recalled Component : The fuel hoses are visibly different and have a unique part number.

Identify How/When Recall Condition was Corrected in Production : Units on stop ship are being remedied prior to their release. The effective date of the stop ship is July 21, 2021.

Recall Schedule :

Description of Recall Schedule : The Shyft Group, Inc. does not have a dealer network for the motorhome chassis and relies on the final stage manufacturers to notify their dealers.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : SEP 03, 2021 - SEP 03, 2021

* NR - Not Reported